

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 25.07.2022

TO : **NTUC** MOTOR CLAIMS DEPTS
VEHICLE NO : **CB8125A**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 10.07.2022
TIME OF ACCIDENT : 18:05HRS

GRH 223209077
Xiao Chen

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,054.20	\$ 2,054.20
2	TAILGATE LOGO <i>new</i>	1	\$ 75.10	\$ 75.10
3	TAILGATE 'HIACE' EMBLEM <i>new</i>	1	\$ 57.40	\$ 57.40
4	TAILGATE 'GL' EMBLEM <i>new</i>	1	\$ 58.40	\$ 58.40
5	TAILGATE CENTER MOULDING (CHROME) <i>new</i>	1	\$ 467.30	\$ 467.30
6	TAILGATE INNER BOARD (LOWER) <i>new</i>	1	\$ 271.80	\$ 271.80
7	TAILGATE WEATHERSTRIP <i>lit</i>	1	\$ 329.60	\$ 329.60
8	TAILGATE WEATHERSTRIP PROTECTOR <i>new</i>	1	\$ 178.90	\$ 178.90
9	TAILGATE INNER LOCK COVER <i>new</i>	1	\$ 75.40	\$ 75.40
10	TAILGATE INNER LOCK <i>new</i>	1	\$ 475.60	\$ 475.60
11	TAILGATE LOWER LOCK	1	\$ 105.00	\$ 105.00
12	TAILGATE STOPPER <i>new</i>	1	\$ 28.00	\$ 28.00
13	TAILLAMP LOWER GARNISH <i>new</i>	2	\$ 110.10	\$ 220.20
14	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 65.00	\$ 130.00
15	REAR BUMPER <i>Dented</i>	1	\$ 395.00	\$ 395.00
16	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00
17	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 542.10	\$ 542.10
18	REAR FLOOR MAT <i>new</i>	1	\$ 1,591.50	\$ 1,591.50

3511.80
2633.85

TOTAL PRICE \$ 7,165.50
LESS 25% \$ 1,791.38
SUB TOTAL PRICE \$ 5,374.13

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

TO : NTUC MOTOR CLAIMS DEPTS
 VEHICLE NO : CB8125A
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 10.07.2022
 TIME OF ACCIDENT : 18:05HRS

1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
4	TAILGATE CENTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
5	TAILGATE INNER BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
6	TAILGATE STICKER 'EMERGENCY DOOR' <i>new</i>	1	\$ 40.00	\$ 40.00	+
7	TAILGATE STICKER 'PULL TO OPEN' <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 40.00	\$ 40.00	10
9	TAILGATE STICKER 'A.W.C' <i>new</i>	1	\$ 40.00	\$ 40.00	20
10	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
11	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	40
12	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
13	TAILLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
14	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	60
15	REAR FLOOR PANEL MAT CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+

TOTAL \$ 1,000.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,800.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600
3	WIRNING, BULB CHECKING	\$ 80.00	30
4	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
5	TRANSFER TAILGATE MECHAISM	\$ 80.00	✓
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50
8	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	50

TO : **NTUC** MOTOR CLAIMS DEPTS
VEHICLE NO : **CB8125A**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 10.07.2022
TIME OF ACCIDENT : 18:05HRS

TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO 9 SPECIFICATION ETC.	\$ 180.00	X
---	-----------	---

1530

TOTAL \$3,740.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,374.13
TOTAL LABOUR COST : \$ 3,740.00
TOTAL REPAIR COST : \$ 10,114.13

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 4363.85

4/s: 3450-

3.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: