

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC22007129/Avy3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	10/10/2022	
	ATTN: FIONA SHE	N		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMC 1265B	Veh. Inspected		SLX 3029E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1181506-001	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		26/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA SIENTA	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MHFZ28H3600051859	Colour		BROWN	
	Odometer	86983 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/50 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	195/50 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	195/50 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	195/50 R16	YOKOHAMA		6 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
					3	
5.	General Information					
	Accident Date	22/07/2022	Inspect Date /	Time	26/07/2022 (01:45 PM)	
	Survey held at	HD PERFECT AUTOWORK PTE LTD				
		8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					