

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts Er	n Automo	obile CS3/LPC22005311/Rqy	
	LONPAC INSURANCE BHD			Ref:	<del>003/LP622005311/y</del> 3	
	300 BEACH ROAD #17-04/07 THE CO		Date:	<del>03/00/2022</del> 25/07/2022		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 2890D	Veh. Inspected	I	SLF 8815P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From	CERALD DOH ENG HUEY NI	Assign Date		25/07/2022	
2.		Vehicle Parti	culars & Conditi	on		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
١.		Description of Damages				
5.	General Information					
	Accident Date	02/06/2022	Inspection Dat			
	Survey held at	38 WOODLANDS RD #06-03, WOODLANDS IND P			1	
	Repairer	HWA PENG AUTO SERVICE (1996)				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					