

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0618/2022/EQ
DATE : 22-Jul-22
WIP : 32821

Xiao Chen

05 days.

\$17253.20.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

OWNER'S NAME : MR ANG KIM HOCK
ADDRESS : 5 JALAN HAJUJAH
#01-02, LANDBAY CONDOMINIUM

TELEPHONE : HP +65 96286102
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070091126-02
VEHICLE NO : **SMT 4166 U**
MODEL CODE : A4 SEDAN 2.0 TFSI
MODEL YEAR : 10/6/2020
ENGINE NO : CVK 086932
CHASSIS NO : WAUZZZF46KA110993
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Jul-22
PLACE OF ACCIDENT : BEDOK SOUTH AVE 1

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR A ACCIDENT VEHICLE SMT 4166 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUT SIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ✓ 250 ✓	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS HEADLIGHT AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED ✓ ✓	\$ 2,800.00 ✓ 1500 ✓	✓
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET. ✓	\$ 2,600.00 ✓ 1650 ✓	✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 6,422.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 4166 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1 S	2,377.00 ✓	1901.60
2	FRONT BUMPER GRILLE - CENTER <i>new</i>	1 S	219.00 ✗	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>torn</i>	1 S	254.00 ?	203.20 ✓
4	FRONT AIR GUIDE - RH	1 S	72.00 ✓	57.20
5	FRONT AIR GUIDE GRILLE - RH <i>Missing</i>	1 S	151.00 ✓	120.40
6	FRONT BUMPER GUIDE SECTION - RH <i>could</i>	1 S	41.00 ?	32.24 ✓
7	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1 S	139.00 ✗	
8	FRONT BUMPER REINFORCEMENT BEAM <i>Not New</i>	1 S	899.00 ✗	
9	LOCK CARRIER TOP BRACKET <i>new</i>	1 S	154.00 ?	✗
10	FRONT PARKING AID SENSOR - INNER / OUTER <i>Missing</i>	1 S	265.00 ✓	212
11	FRONT PARKING AID SEAL RING <i>new</i>	4 S	10.00 ✓	8
12	FRONT FENDER - RH <i>Dented</i>	1 S	861.00 ✓	688.80
13	FRONT FENDER CLOSING ELEMENT - RH <i>Not new</i>	1 S	81.00 ?	✗
14	FRONT FENDER BRACKET - RH <i>Not new</i>	1 S	41.00 ?	✗
15	FRONT FENDER RIVET <i>new</i>	6 S	23.00 ✓	18.24
16	FRONT FENDER BRACE - RH <i>Not new</i>	1 S	132.00 ?	✗
17	FRONT WHEEL SPOILER - RH <i>torn</i>	1 S	82.00 ✓	65.12
18	FRONT WHEEL SPOILER TRIM - RH <i>torn</i>	1 S	40.00 ✓	32
19	FRONT STONE CHIP GUARD - RH <i>new</i>	1 S	57.00 ✗	
20	FRONT WHEEL HOUSING LINER - RH <i>torn</i>	1 S	262.00 ✓	209.60
SUB TOTAL SPARE PARTS			\$ 6,160.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 4166 U

L/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT AND REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>HP</i>	1	\$	149.00	? X
22	FRONT HEADLIGHT - RH <i>lit</i>	1	\$	8,293.00	✓ 6635.20
23	FRONT HEADLIGHT LIFT CYLINDER - RH <i>Damaged</i>	1	\$	231.00	✓ 184.40
24	FRONT HEADLIGHT BRACKET <i>Re n</i>	1	\$	7.00	? X
25	BONNET <i>Dented</i>	1	\$	3,425.00	✓ 2740
26	BONNET IMPACT PROTECTION - LH / RH / CENTER <i>new</i>	3	\$	93.00	✓ 73.20
27	SUNDRIES <i>Re n</i>		\$	300.00	? X
TOTAL SPARE PARTS		:	\$	18,658.00	
TOTAL LABOUR CHARGES		:	\$	6,422.00	
GRAND TOTAL		:	\$	25,080.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (C K) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *19/07/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 5 Days.* 

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

- LKK Auto Consultants** hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: