Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

Allianz Insurance Singapore Pte. From: LKK Auto Consultants Pte Ltd To:

Ltd.

79 Robinson Road #09-01

Singapore 068897

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: JANICE KOH Date: 28 Jul 2022

Preliminary Advice

Vehicle No : SMQ2271C **Accident Date** : 18/07/2022

: HYUNDAI AD AVANTE Policy No. Make

SP2000532132-

01

Assignment **Excess** : 27/07/2022 : S\$0.00

Date

Date of : 27/07/2022 Est. Duration of

: 5 Inspection Repair

Inspection At: SHU FATT AUTO WORKS (HQ)

BLOCK 1009 BUKIT MERAH LANE 3, #01-90

SINGAPORE 159723

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 6,909.00 **Revised Amount** :S\$ 4,338.30 Check Items (Estimated) :S\$ 1,188.10 Total :S\$ 5,526.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

:S\$ 83,000.00 Pre-Accident Value COE / PARF Rebate :S\$ 32,986.00 Salvage Value :S\$

Margin for Repair :S\$ 50,014.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: THE VEHICLE REPAIR ON PART BY PART BASIS AS THE VEHICLE USED LESS THAN 3 YEARS.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.