

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jul 2022)
 Parts: 143 HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Shu Fatt Auto Works/SMQ2271C/26/07/2022 13:08
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet / <i>DD</i>	0.00	0.00	*600.00 F ✓
2	1		*Front bonnet insulator <i>CRU</i> NN	0.00	0.00	*105.00 F X
3	12		*Front bonnet insulator clips <i>ACC</i> NN	0.00	0.00	*36.00 F X
4	1		*Front bonnet lock X NN	0.00	0.00	*70.00 F X
5	1		*Left front bonnet hinge <i>BT</i>	0.00	0.00	*35.00 F 36 ✓
6	1		*Right front bonnet hinge <i>BT</i>	0.00	0.00	*35.00 F 36 ✓
7	1		*Left front headlight <i>BR</i>	0.00	0.00	*500.00 F 520 ✓
8	1		*Right front headlight <i>BR</i>	0.00	0.00	*500.00 F 520 ✓
9	1		*Front grille <i>BR</i>	0.00	0.00	*280.00 F ✓
10	1		*Front grille emblem <i>ACC</i> NN	0.00	0.00	*30.00 F X
11	8		*Front grille clips <i>ACC</i> NN	0.00	0.00	*24.00 F X
12	1		*Front bumper <i>br</i>	0.00	0.00	*360.00 F 430 ✓
13	1		*Front bumper top rubber <i>CRU</i>	0.00	0.00	*20.00 F ✓
14	1		*Front bumper foam <i>BR</i> ? NN	0.00	0.00	*65.00 F ✓
15	1		*Front bumper reinforcement <i>ACC</i> NN	0.00	0.00	*240.00 F X
16	16		*Front bumper clips <i>ACC</i> NN	0.00	0.00	*48.00 F X
17	1		*Left front bumper side retainers <i>BR</i> NN	0.00	0.00	*18.00 F X
18	1		*Right front bumper side retainers <i>BR</i> NN	0.00	0.00	*18.00 F X
19	1		*Front bumper lower garnish ? NN	0.00	0.00	*70.00 F X
20	12		*Front bumper lower garnish clips ? NN	0.00	0.00	*36.00 F X
21	1		*Front number plate garnish <i>BR</i>	0.00	0.00	*60.00 F ✓
22	1		*Front support panel ? NN	0.00	0.00	*280.00 F X
23	1		*Front support top garnish <i>BR</i>	0.00	0.00	*45.00 F ✓
24	8		*Front support top garnish clips <i>ACC</i> NN	0.00	0.00	*24.00 F X
25	16		*Left front fender cowling clips <i>BR</i> X NN	0.00	0.00	*48.00 F X
26	16		*Right front fender cowling clips <i>BR</i> X NN	0.00	0.00	*48.00 F X
27	1		*Front air resonator ? NN	0.00	0.00	*65.00 F X
28	1		*Coolant ? NN	0	0.00	*28.00 FS X
29	1		*Front number plate <i>BR</i>	0	0.00	*55.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (S\$) 3,743.00
 + Margin on L,N Items 10.00% (S\$) 366.00
 Total Parts (S\$) 4,109.00

Shu Fatt Auto Works/SMQ2271C/26/07/2022 13:08. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
Miscellaneous Items				
1	1	To remove, replace aircon condenser, fan assembly, fill air con freon & assembly.	NN	150.00 X
2	1	To remove, replace radiator, fill coolant assembly.	NN	250.00 X
Sub Total (S\$)				400.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To respray damaged parts.	New	800 1,200.00
Labour Items			
2	To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt fender, left frt fender panel, rt frt fender panel, renew frt bonnet, frt support panel, frt lights, grille, frt bumper & assembly.	New	400 1,200.00
Gross Labour Cost (S\$)			2,400.00

Shu Fatt Auto Works/SMQ2271C/26/07/2022 13:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve CLKK)
27/7/22, 3-3pm

OP- MNL
Ex cell- ?
PIP

My Bal y
5 Lys

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: