

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 26.07.2022

TO : LONPAC MOTOR CLAIMS DEPTS
VEHICLE NO : SLD3398U
MODEL : TOYOTA VELLFIRE
DATE OF ACCIDENT : 26.07.2022
TIME OF ACCIDENT : 14:00HRS

JTNGF3DH 908004365

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEADLAMP (LED) LH <i>included</i>	1	\$ 3,638.00	\$ 3,638.00
2	FRONT FENDER LH <i>Dented</i>	1	\$ 1,095.00	\$ 1,095.00
3	FRONT FENDER COWLING LH <i>Rehnd</i>	1	\$ 279.00	\$ 279.00
4	FRONT FENDER LOWER GUARD LH <i>He n</i>	1	\$ 397.00	\$ 397.00
5	FRONT ABS SENSOR LH <i>not in</i>	1	\$ 380.00	\$ 380.00
6	FRONT WHEEL RIM LH <i>Got</i>	1	\$ 1,800.00	\$ 1,800.00
7	FRONT ANTI ROLL BAR LINKAGE LH <i>not in</i>	1	\$ 195.00	\$ 195.00
8	FRONT KNUCLE ARM LH <i>He n</i>	1	\$ 680.00	\$ 680.00
9	FRONT WHEEL HUP WITH BEARING LH <i>He n</i>	1	\$ 670.00	\$ 670.00
10	FRONT SHOCK ABSORBER LH <i>He n</i>	1	\$ 540.00	\$ 540.00
11	FRONT LOWER ARM LH <i>He n</i>	1	\$ 469.00	\$ 469.00
12	FRONT STEERING RACK AND PINION <i>He n</i>	1	\$ 1,950.00	\$ 1,950.00
13	FRONT DRIVESHAFT LH <i>He n</i>	1	\$ 1,580.00	\$ 1,580.00
14	FRONT DOOR PILLAR (OUTER) <i>Reps</i>	1	\$ 985.00	\$ 985.00
15	FRONT DOOR PILLAR QUARTER GLASS C/W MOULDING LH <i>He n</i>	1	\$ 465.00	\$ 465.00
16	FRONT WINDSCREEN MOULDING <i>He n</i>	1	\$ 261.00	\$ 261.00
17	SIDE MIRROR LH <i>Paint</i>	1	\$ 1,655.00	\$ 1,499.00
18	FRONT DOOR LH <i>Dented</i>	1	\$ 1,899.00	\$ 1,499.00
19	FRONT DOOR LOWER GUARD LH <i>not in</i>	1	\$ 864.30	\$ 1,037.00
20	FRONT DOOR OUTER STRIP LH <i>He n</i>	1	\$ 107.30	\$ 107.30
21	FRONT DOOR HINGE LH <i>He n</i>	2	\$ 73.29	\$ 73.29
22	FRONT DOOR INNER LOCK LH <i>He n</i>	1	\$ 534.70	\$ 534.70
23	FRONT DOOR INNER TRIM LH <i>He n</i>	1	\$ 1,370.90	\$ 1,370.90
24	FRONT DOOR LOCK CATCHER LH <i>He n</i>	1	\$ 40.50	\$ 40.50
25	FRONT DOOR WEATHER STRIP LH <i>He n</i>	1	\$ 171.20	\$ 171.20

8319.30

6389.47

SN: 1200

TOTAL PRICE \$ 21,716.89
LESS 25% \$ 5,429.22
SUB TOTAL PRICE \$ 16,287.67

TO : **LONPAC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD3398U**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 26.07.2022
 TIME OF ACCIDENT : 14:00HRS

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER LOWER INNER GARNISH CLIP (SE) <i>Neu</i>	1	\$ 50.00	\$ 50.00
3	RADIATOR GRILLE CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00
4	HEADLAMP CHROME MOULDING (SPECAIL TYPE) <i>Neu</i>	1	\$ 480.00	\$ 480.00
4	FRONT FENDER COWLING LH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00
5	FRONT DOOR PILLAR SEALANT LH <i>Neu</i>	1	\$ 120.00	\$ 120.00
6	FRONT WINDSCREEN SEALANT LH <i>Neu</i>	1	\$ 80.00	\$ 80.00
7	FRONTWINDSCREEN INNER SHIELD LH <i>Neu</i>	1	\$ 80.00	\$ 80.00
8	FRONT DOOR SEALANT LH <i>Neu</i>	1	\$ 60.00	\$ 60.00
9	FRONT DOOR PROTECTOR CLIP LH (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00
10	FRONT DOOR INNER TRIM CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00
11	FRONT WHEEL TYRE LH <i>Neu</i>	1	\$ 450.00	\$ 450.00
12	PRIVATE DECAL (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00
13	BRAKE OIL <i>Neu</i>	1	\$ 40.00	\$ 40.00

TOTAL \$ 1,700.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,200.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	600
3	TUFF COAT	\$ 250.00	50
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	X
6	REMOVE AND REFIX FRONT WINDSCREEN	\$ 180.00	X
7	REMOVE AND REFIX FRONT QUARD GLASS LH	\$ 120.00	40
8	REMOVE AND REFIX DASHBOARD	\$ 650.00	X
9	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X
10	TRANFER FRONT DOOR MECHANISM LH	\$ 80.00	✓
11	REMOVE & REINSTALL FRONT WINDOW GLASS LH	\$ 80.00	50

TO : LONPAC MOTOR CLAIMS DEPTS
VEHICLE NO : SLD3398U
MODEL : TOYOTA VELLFIRE
DATE OF ACCIDENT : 26.07.2022
TIME OF ACCIDENT : 14:00HRS

12	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
13	RESET ABS LIGHT	\$ 350.00	X
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL

1450

\$6,560.00

Adrian Lj
h/s 27/07/22.
05 Days

ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,987.67
TOTAL LABOUR COST : \$ 6,560.00
TOTAL REPAIR COST : \$ 24,547.67

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 9409.47
h/s: 7-5/16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: