



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET		Ref: CS/ASM22007166/Tcy3m4 Date: 13/03/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 4457P	Veh. Inspected	FBB 8293J
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M047L6	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	27/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YAMAHA X1R	c.c	135
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	4S3503316	Colour	BLACK
Odometer	9606 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	70/90R17	MAXXIS	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	70/90R17	MAXXIS	5 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	16/07/2022	Inspection Date	28/07/2022
Survey held at	25 KAKI BUKIT ROAD 4 #03-79 SINGAPORE 417800		
Repairer	EQBH PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	