

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YACOOB HUSSAIN S/O ALI IBRAHIM
BLK 395 TAMPINES AVE 7 #02-283
SINGAPORE 520395

TP Chin.

Xiao Chin.

TAX INVOICE

Repair Code : CLM17298

Date in : 26/07/2022

Vehicle Num. : SME9965B

Model : SUZUKI VITARA 1.6 GLX 6AT 2WD

Chassis/Eng# : TSMLYD21S00516678/M16A2280204

Contact : 98250902, 92960561

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>Dented</i>	1	764.00	764.00 ✓
FRONT BONNET <i>Dented</i>	1	989.00	989.00 ✓
FRONT BONNET HINGES L/R <i>3 new</i>	2	27.00	54.00 X
FRONT BONNET INSULATOR MAT	1	220.00	220.00 X
FRONT BONNET MECHANISM LOCK <i>Damaged</i>	1	176.00	176.00 ✓
FRONT BONNET RUBBER SEAL <i>new</i>	1	29.00	29.00 X
FRONT BUMPER <i>Deformed</i>	1	1092.00	<i>982</i> 1,092.00 ✓
FRONT BUMPER CENTER PROTECTOR GARNISH <i>deh d</i>	1	195.50	195.50 ✓
FRONT BUMPER DAYLIGHT L/R <i>new</i>	2	750.00	1,500.00 X
FRONT BUMPER FOGLAMP BRACKET L/R <i>cracked</i>	2	55.00	110.00 ✓
FRONT BUMPER FOGLAMP L/R <i>cracked</i>	2	201.50	403.00 ✓
FRONT BUMPER FOGLAMP WIRE HARNESS <i>new</i>	1	225.00	225.00 X
FRONT BUMPER INNER AIR GUIDE L/R (BOTTOM) <i>Deformed</i>	2	35.50	71.00 ✓
FRONT BUMPER INNER AIR GUIDE L/R (TOP)	2	34.10	68.20 ✓
FRONT BUMPER LOWER COVER <i>Deformed</i>	1	216.20	216.20 ✓
FRONT BUMPER LOWER PROTECTOR GARNISH <i>Deformed</i>	1	190.50	190.50 ✓
FRONT BUMPER PARKING SENSOR <i>2 pieces damaged</i>	<i>2</i>	155.00	<i>310</i> 620.00 ✓
FRONT BUMPER PARKING SENSOR COVER <i>new</i>	4	20.00	80.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YACOOB HUSSAIN S/O ALI IBRAHIM
BLK 395 TAMPINES AVE 7 #02-283
SINGAPORE 520395

Contact : 98250902, 92960561

TAX INVOICE

Repair Code : CLM17298

Date in : 26/07/2022

Vehicle Num. : SME9965B

Model : SUZUKI VITARA 1.6 GLX 6AT 2WD

Chassis/Eng# : TSMLYD21S00516678/M16A2280204

FRONT BUMPER REINFORCEMENT	<i>Dented</i>	1	816.50	729	816.50	✓
FRONT BUMPER SIDE RETAINER L/R	<i>cracked</i>	2	28.70		57.40	✓
FRONT BUMPER TOW HOOK COVER	<i>Not No</i>	1	18.00		18.00	X
FRONT FENDER ARCH GARNISH L/R		2	98.00		196.00	X
FRONT GRILLE	<i>Cracked</i>	1	493.00		493.00	✓
FRONT GRILLE LOGO	<i>New</i>	1	332.00	65	332.00	✓
FRONT GRILLE LOWER MOULDING L/R	<i>RH</i>	<i>2</i>	30.00		60.00	✓
FRONT GRILLE UPPER MOULDING L/R	<i>RH.</i>	<i>2</i>	30.00		60.00	✓
FRONT HEADLAMP L/R	<i>cracked.</i>	2	2487.00		4,974.00	✓
FRONT HEADLAMP LOWER BRACKET L/R	<i>cracked.</i>	2	32.20		64.40	✓
FRONT HEADLAMP SIDE PANEL L/R	<i>3 pieces</i>	2	105.00		210.00	X
FRONT TOP PANEL		1	330.00		330.00	X
FRONT TOP PANEL GARNISH	<i>Deformed</i>	1	79.00		79.00	✓
REAR BUMPER	<i>Distorted.</i>	1	1120.00	871	1,120.00	✓
REAR BUMPER INNER GARNISH L/R	<i>Deformed</i>	2	74.70		149.40	✓
REAR BUMPER LOWER LID CENTER COVER	<i>Missing</i>	1	66.70		66.70	✓
REAR BUMPER LOWER LID GARNISH	<i>Distorted</i>	1	357.00		357.00	✓
REAR BUMPER REFLECTOR L/R	<i>cracked</i>	2	32.50		65.00	✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YACOOB HUSSAIN S/O ALI IBRAHIM
BLK 395 TAMPINES AVE 7 #02-283
SINGAPORE 520395

Contact : 98250902, 92960561

TAX INVOICE

Repair Code : CLM17298

Date in : 26/07/2022

Vehicle Num. : SME9965B

Model : SUZUKI VITARA 1.6 GLX 6AT 2WD

Chassis/Eng# : TSMLYD21S00516678/M16A2280204

REAR BUMPER REINFORCEMENT	<i>Dented</i>	1	292.00	292.00	✓
REAR BUMPER REVERSE SENSOR	<i>2 pieces damaged</i>	<i>1/2</i>	155.00	620.00	<i>310</i>
REAR BUMPER REVERSE SENSOR COVER	<i>Nec</i>	4	20.00	80.00	✓
REAR BUMPER REVERSE SENSOR WIRE HARNESS	<i>Not Nec</i>	1	220.00	220.00	X
REAR BUMPER SIDE RETAINER L/R	<i>cracked</i>	2	29.10	58.20	✓
REAR END PANEL	<i>Dented</i>	1	477.30	477.30	✓
REAR END PANEL AIR VENT L/R	<i>cracked</i>	2	45.70	91.40	✓
REAR END PANEL ANTENNA SENSOR	<i>Damaged</i>	1	142.00	142.00	✓
REAR END PANEL INNER TOP GARNISH	<i>Deformed</i>	1	178.30	178.30	✓
REAR FENDER ARCH GARNISH L/R	<i>Not Nec</i>	2	95.00	190.00	X
REAR FENDER INNER TRIM GARNISH L/R	<i>cracked</i>	2	495.00	990.00	<i>876</i>
REAR SPARE TYRE INNER TOP BOARD COVER	<i>torn</i>	1	181.50	181.50	✓
REAR TAILGATE	<i>Distorted</i>	1	1155.75	1,155.75	<i>1005</i>
REAR TAILGATE 'LOGO' EMBLEM	<i>} Nec</i>	1	35.20	35.20	✓
REAR TAILGATE 'SUZUKI' EMBLEM		1	28.70	28.70	✓
REAR TAILGATE 'VITARA' EMBLEM		1	34.30	34.30	✓
REAR TAILGATE DAMPER L/R	<i>} Not Nec</i>	2	105.00	210.00	X
REAR TAILGATE HINGES L/R		2	50.00	100.00	X

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YACOOB HUSSAIN S/O ALI IBRAHIM
BLK 395 TAMPINES AVE 7 #02-283
SINGAPORE 520395

Contact : 98250902, 92960561

TAX INVOICE

Repair Code : CLM17298

Date in : 26/07/2022

Vehicle Num. : SME9965B

Model : SUZUKI VITARA 1.6 GLX 6AT 2WD

Chassis/Eng# : TSMLYD21S00516678/M16A2280204

REAR TAILGATE INNER PULL GARNISH	<i>new</i>	1	25.00	25.00	X
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	<i>new</i>	2	20.00	40.00	X
REAR TAILGATE INNER SIDE STOPPER L/R	<i>new</i>	2	22.00	44.00	X
REAR TAILGATE INNER TRIM GARNISH	<i>cracked</i>	1	390.50	390.50	✓
REAR TAILGATE MECHANISM LOCK	<i>Damaged</i>	1	203.00	203.00	✓
REAR TAILGATE MECHANISM LOCK STRIKER	<i>new</i>	1	20.00	20.00	X
REAR TAILGATE MECHANISM LOCK STRIKER COVER	<i>De band</i>	1	22.00	22.00	✓
REAR TAILGATE NUMBER PLATE LAMP L/R	<i>new</i>	2	30.00	60.00	X
REAR TAILGATE OPENER BUTTON SENSOR	<i>Damaged</i>	1	137.10	137.10	✓
REAR TAILGATE OPENER SENSOR SWITCH	<i>Damaged</i>	1	136.20	136.20	✓
REAR TAILGATE OUTER GARNISH	<i>cracked</i>	1	373.70	373.70	✓
REAR TAILGATE REFLECTOR GASKET SEAL L/R	<i>new</i>	2	30.00	60.00	✓
REAR TAILGATE REFLECTOR L/R	<i>cracked</i>	2	327.75	655.50	✓
REAR TAILGATE WEATHER STRIP SEAL	<i>cut</i>	1	175.90	175.90	✓
REAR TAILGATE WINDSCREEN MOULDING	<i>new</i>	1	74.70	74.70	✓
REAR TAILGATE WIPER ARM	<i>new</i>	1	48.00	48.00	X
REAR TAILGATE WIPER ARM COVER	<i>new</i>	1	18.00	18.00	X
REAR TAILGATE WIPER MOTOR	<i>Damaged</i>	1	362.25	362.25	✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

YACOOB HUSSAIN S/O ALI IBRAHIM
 BLK 395 TAMPINES AVE 7 #02-283
 SINGAPORE 520395

TAX INVOICE

Repair Code : CLM17298

Date in : 26/07/2022

Vehicle Num. : SME9965B

Model : SUZUKI VITARA 1.6 GLX 6AT 2WD

Chassis/Eng# : TSMLYD21S00516678/M16A2280204

Contact : 98250902, 92960561

REAR TAILLAMP L/R	ht	19867.05	2	401.50	724	803.00
REAR TAILLAMP PANEL L/R	Rings	16886.99	2	138.00		276.00
Subtotal before discount						25,461.30
Percentage discount 15%						3,819.20
Sub-total 1						21,642.11
FRONT BONNET INSULATOR MAT CLIPS - SET	NN		1	50.00		50.00
FRONT BUMPER CLIPS - SET	New		1	50.00		50.00
FRONT GRILLE CLIPS - SET	new		1	30.00		30.00
FRONT NUMBER PLATE	Dented		1	25.00		25.00
FRONT NUMBER PLATE HOLDER	Deformed		1	50.00	30	50.00
RADIATOR COOLANT	New		1	60.00	40	60.00
REAR BUMPER CLIPS - SET	new		1	50.00	30	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	New		1	30.00	10	30.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	New		2	50.00		100.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	New		1	80.00	30	80.00
REAR TAILGATE NUMBER PLATE	Dented		1	25.00		25.00
REAR TAILGATE NUMBER PLATE HOLDER	Deformed		1	50.00	30	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	new		1	40.00	20	40.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YACOOB HUSSAIN S/O ALI IBRAHIM
BLK 395 TAMPINES AVE 7 #02-283
SINGAPORE 520395

TAX INVOICE

Repair Code : CLM17298

Date in : 26/07/2022

Vehicle Num. : SME9965B

Model : SUZUKI VITARA 1.6 GLX 6AT 2WD

Chassis/Eng# : TSMLYD21S00516678/M16A2280204

Contact : 98250902, 92960561

REAR TAILGATE WINDSCREEN SEALANT <i>nu</i>	1	80.00	60 80.00
REAR TAILLAMP CLIPS L/R - SET <i>nu</i>	2	30.00	40 60.00
Subtotal before discount			780.00
Percentage discount 0%			0.00
Sub-total 2			780.00
Parts-total			22,422.11

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	120	150.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	80.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80	140.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1300	1,400.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	600	1,400.00
To remove and reinstall exhaust pipe.	X	100.00 X
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1800	2,000.00
To apply anti-rust chemical on repaired and replaced panel.	100	150.00
To remove, reinstall tailgate mechanism and check for function	✓	80.00
Labour Total		5,650.00
Parts & Labour Total		28,072.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 6

total: 21286.99
h/s: 171K

12 Days

171K
12 days