

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	/198R GST Reg. No.	19-9607	198-R	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	_	Ref:	CS/AGI22007172/Kvy3m4	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	13/10/2022	
				Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJJ 2323J	Veh. Inspected		SLS 701T	
	Policy No.	P10108404R04	Coverage (\$)		0.00	
	Claim No.	C10016572/JT	Excess (\$)		0.00	
	Assign From	SALIZAWATI	Assign Date		27/07/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES A180D (A)	c.c		1461	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	WDD1760122J628283	Colour		METALLIC GREY	
	Odometer	30879 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	GOODYEAR		7 mm	
	L/H Front Tyre	225/40 R18	GOODYEAR		7 mm	
	R/H Rear Tyre	225/40 R18	GOODYEAR		7 mm	
	L/H Rear Tyre	225/40 R18	GOODYEAR		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	25/07/2022	Inspection Date)	02/08/2022	
	Survey held at 160 Sin Ming Drive #06-03 Sin Ming Autocity					
	Repairer	MBM WHEELPOWER PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: