



南方摩哆 Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

26 July 2022

MS First Capital Insurance Limited
36 Robinson Road #16-01
City House
Singapore (068877)

Dear Sirs,

RE: Cost of repair to Yamaha Nmax155 ABS CVT -FBR8549M

1pc of Rear Fork	S\$	480.00
1pc of Exhaust Pipe Cover		140.00
1pc of Radiator Cover		85.00
1pc of Body Guard		180.00
1pc of Lower Cowling		135.00
1pc of Front Faring Side LH		215.00
1pc of Mirror		45.00
1pc of Rear Box Bracket		85.00
1pc of Centre Fairing		75.00
		<hr/>
		1,440.00
	Less 10%	144.00
		<hr/>
	Nett	1,296.00
	Labour	200.00
		<hr/>
		<u>\$1,496.00</u>

Yours Faithfully,
Southern Motor



Date: 26 July 2022

Southern Motor
Blk 1006 Bukit Merah Lane 2
#01-10
Singapore 159762

Motor Claims Department
MS First Capital Insurance Limited
36 Robinson Road #16-01
City House
Singapore 068877

Dear Sirs,

RE: ACCIDENT INVOLING FBR8549M AND SHC4535L ALONG
Towards Fort Canning ON 01-06-2022 AT 11:35AM

Please be informed that the above-said motorcycle bearing registration no: FBR8549M was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,



Enc.