



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 8549M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FORK	* CHECK	480.00	-
1	EXHAUST PIPE COVER	CUT	140.00	140.00
1	RADIATOR COVER	CUT	85.00	85.00
1	BODY GUARD	BENT	180.00	180.00
1	LOWER COWLING	CUT	135.00	135.00
1	FRONT FAIRING SIDE LH	CUT	215.00	215.00
1	MIRROR	CUT	45.00	45.00
1	REAR BOX BRACKET	NOT NECESSARY	85.00	-
1	CENTRE FAIRING	CUT	75.00	75.00
	LESS 10% DISCOUNT		-144.00	-87.50
			1,296.00	787.50
	<u>LABOUR</u>			
	LABOUR.		200.00	150.00
			200.00	150.00
	GRAND TOTAL		1,496.00	937.50
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$432.00 NETT)			937.50

Report Ref No. CS/SMR22007173/Evy3m4

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.