

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22007175/TVY3Q2**Date:** 27/09/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS004571		
Claimant Vehicle No :	SHD8808T	Insured Vehicle No :	SLC2561B		
Date of Loss:	26/07/2022	Nature of Claim:	TP	Claim No:	M2203955

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD8808T	Engine No:	65195035108323
Make & Model:	MERCEDES-BENZ V220D, 2.1 D LONG (A)	Chassis No:	WDF44781323611470
Reg. Date:	06/08/2019 (Man. Year: 2019)	Odometer:	226882 km
Colour:	White		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	GTRadial 6 mm	Rear Left Side:	GTRadial 6 mm
Front Right Side:	GTRadial 6 mm	Rear Right Side:	GTRadial 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,939.99	2,192.27	2,747.72	55.62
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,200.00	1,250.00	950.00	43.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,150.99	3,453.27	3,697.72	51.71
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	7,150.99	2,750.00	4,400.99	61.54
+ GST 7.00/7.00% (S\$)	500.57	192.50	308.07	61.54
Nett Amount (S\$)	7,651.56	2,942.50	4,709.06	61.54

INSPECTION

Date of Assignment:	27/07/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	27/07/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Sep 2022)	
Parts:	N/A	MERCEDES-BENZ V220D 2.1 D LONG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD8808T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	3,951.98 FL	*2,329.38 FL
2	1		*REAR BUMPER ASSY	Repair	1,372.00 FL	*- FL
3	1		*TAIL GATE LOCK ASSY	Not Necessary	273.40 FL	*- FL
4	1		*TAIL GATE EMBLEM - V220	Necessary	78.00 FL	*78.00 FL
5	1		*TAIL GATE EMBLEM - MERC STAR	Necessary	45.46 FL	*45.46 FL
6	1		*TAIL GATE MAXICAB LOGO	Necessary	80.00 F	*80.00 F
7	1		*REAR BUMPER MAT	Deformed	50.00 F	*50.00 F
8	1		*REAR NUMBER PLATE	Bent	50.00 F	*50.00 F
9	1		*TAIL GATE WEATHERSTRIP	Not Necessary	166.65 FL	*- FL
10	2		*WINDSCREEN SEALANT	Necessary	50.00 F	*50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,117.49	2,682.84
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,177.50	490.57
Total Parts (\$\$)	4,939.99	2,192.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	600.00
2	SPRAYPAINT	New	600.00	500.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
4	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
Gross Labour Cost (\$\$)			2,200.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >