

ASS. REC. BY: Taufik

REF:

CS / TM 2200175 / Tv3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: SLC 2561BPolicy No. MS00457Claims No. M2203955

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Sumen

Vehicle: IN / OUT

Veh No: SHD8808T Yr Regn: 2019 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz V220 c.c. 2148Colour: white A/C: Insured / Std / NI / NASp. Reading: 226882 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDF 44781323611470Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 65 R16R: u u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GT Radial

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/7/2022 D.O.I. 27/7/22Survey held at Comfort Logis

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

21/9/22 Taufikh informed LS \$2750 (Red 4400.99, 61%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 21/9/22-typist

Rep. Format: Merimen

Lump Sum / t.B.h. / \$2750

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

Jumani
(PIP)

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/07/2022
Vehicle Reg. No.:	SHD8808T	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	MERCEDES-BENZ V220D, 2.1 D LONG (A)	Vehicle Reg. Date:	06/08/2019
Vehicle Colour:	WHITE	Gen Condition:	GOOD
Engine No:	65195035108323	Chassis No:	WDF44781323611470
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	4,939.99
Miscellaneous Items	11.00
Labour	2,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,150.99
+ GST 7.00% (S\$)	500.57
Nett Amount (S\$)	7,651.56

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 27 Jul 2022)**Parts:** N/A MERCEDES-BENZ V220D 2.1 D LONG (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD8808T/27/07/2022 13:33**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAIL GATE	20.00	0.00	bt ✓ *3,951.98 FL
2	1		*REAR BUMPER ASSY	20.00	0.00	rs ✓ *1,372.00 FL
3	1		*TAIL GATE LOCK ASSY	20.00	0.00	? *273.40 FL
4	1		*TAIL GATE EMBLEM - V220	20.00	0.00	rec ✓ *78.00 FL
5	1		*TAIL GATE EMBLEM - MERC STAR	20.00	0.00	rec ✓ *45.46 FL
6	1		*TAIL GATE MAXICAB LOGO	0.00	0.00	rec ✓ *80.00 F
7	1		*REAR BUMPER MAT	0.00	0.00	rec ✓ *50.00 F
8	1		*REAR NUMBER PLATE	0.00	0.00	bt ✓ *50.00 F
9	1		*TAIL GATE WEATHERSTRIP	20.00	0.00	? *166.65 FL
10	2		*WINDSCREEN SEALANT	0.00	0.00	rec ✓ *50.00 F

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	6,117.49
- List Item Discount on L Items (S\$)	1,177.50
Total Parts (S\$)	4,939.99

ComfortDelGro Engineering Pte Ltd/SHD8808T/27/07/2022 13:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

✓

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	\$400/day	New	600	1,400.00
2	SPRAYPAINT	\$250/paint	New	500	600.00
3	REMOVE/REFIX REVERSE SENSOR		New	30	80.00
4	REMOVE/REFIX REAR WINDSCREEN GLASS		New	✓	120.00

Gross Labour Cost (\$\$)

2,200.00

ComfortDelGro Engineering Pte Ltd/SHD8808T/27/07/2022 13:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanaka 97445749
 WP 27/7/22 @ 430pm
 Repair before paint
 Tanaka@lkkauto.com
 03 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 27.07.2022 12:07

Page : 1

m: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC No: **305524646**

OMER
S CITYCAB PTE LTD
OMER NO. 7010070
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)
(P)


JUNT CARD NO.

REGN NO: SHD8808T	MILEAGE
MAKE: MERCEDES BENZ	FUEL E.....1/2.....F
MODEL V-CLASS CDI 2.2L	DATE/TIME IN 27.07.2022 09:45
YR OF MANU. 06.08.2019	TARGET DATE
CHASSIS CODE WDF44781323611470	COMPLETION DATE/TIME:

ident Date: 26.07.2022
URE: 3P 26.07.22

JOB DESCRIPTION

O LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

: SHD8808T

JU TOKIO

Vehicle No.:

SHD8808T

ervice Advisor

Signature/Date

Name of Service Advisor

Date

ned to Service Reception upon collection

To be kept by Security Guard