

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

Veron

DATE : 26.07.2022

TO : **MS FIRST CAPITAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SFX7391C**
MODEL : **FIAT BRAVO**
DATE OF ACCIDENT : 25.07.2022
TIME OF ACCIDENT : 17:55HRS

ZFA 19800004103194

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---|-----|-----------------|------------------|
| 1 | FRONT BUMPER UPPER <i>Dented</i> | 1 | \$ 697.80 | \$ 697.80 |
| 2 | FRONT BUMPER LOWER <i>New</i> | 1 | \$ 469.20 | \$ 469.20 |
| 3 | FRONT BUMPER FOGLAMP LH <i>New</i> | 1 | \$ 439.80 | \$ 439.80 |
| 4 | FRONT BUMPER FOGLAMP COVER LH <i>New</i> | 1 | \$ 142.90 | \$ 142.90 |
| 5 | FRONT BUMPER SIDE RETAINER <i>LH Dented</i> | 2 | \$ 72.30 | \$ 144.60 |
| 6 | FRONT BUMPER SIDE BRACKET <i>New</i> | 2 | \$ 64.80 | \$ 129.60 |
| 7 | HEADLAMP LH <i>Cracked</i> | 1 | \$ 748.70 | \$ 748.70 |
| 8 | HEADLAMP LOWER BRACKET LH <i>Abol n</i> | 1 | \$ 101.40 | \$ 101.40 |
| 9 | FRONT FENDER LH <i>Dented</i> | 1 | \$ 440.00 | \$ 440.00 |
| 10 | FRONT FENDER INNER GARNISH LH <i>New</i> | 1 | \$ 86.70 | \$ 86.70 |
| 11 | FRONT FENDER INNER COWLING LH <i>ton</i> | 1 | \$ 150.00 | \$ 150.00 |
| 12 | FRONT ABS SENSOR <i>New</i> | 1 | \$ 186.30 | \$ 186.30 |
| 13 | FRONT STEERING RACK & PINION <i>New</i> | 1 | \$ 1,954.00 | \$ 1,954.00 |
| 14 | FRONT SHOCK ABSORBER LH <i>Bent</i> | 1 | \$ 301.90 | \$ 301.90 |
| 15 | FRONT LOWER ARM LH <i>Bent</i> | 1 | \$ 460.00 | \$ 460.00 |
| 16 | FRONT KNUCKLE ARM LH <i>Dnt</i> | 1 | \$ 944.00 | \$ 944.00 |
| 17 | FRONT KNUCKLE ARM INNER BEARING LH <i>Dnt</i> | 1 | \$ 294.00 | \$ 294.00 |
| 18 | FRONT WHEEL HUP LH <i>Dented</i> | 1 | \$ 188.00 | \$ 188.00 |
| 19 | FRONT DRIVE SHAFT LH <i>New</i> | 1 | \$ 1,855.30 | \$ 1,855.30 |
| 20 | SIDE MIRROR LH <i>Dented</i> | 1 | \$ 1,386.10 | \$ 1,386.10 |

5090.70

4581.63

TOTAL PRICE \$ 11,120.30
LESS 10% \$ 1,112.03
SUB TOTAL PRICE \$ 10,008.27

1210

Handwritten notes and checkmarks on the right side of the table, including '72.30', '528', and '1210'.

TO : **MS FIRST CAPITAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SFX7391C**
 MODEL : **FIAT BRAVO**
 DATE OF ACCIDENT : 25.07.2022
 TIME OF ACCIDENT : 17:55HRS

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|---|-----|-------------|------------------------|
| 1 | FRONT BUMPER CLIP (SET) <i>new</i> | 1 | \$ 60.00 | \$ 60.00 <i>30</i> |
| 2 | FRONT BUMPER LOWER GARNISH CLIP (SET) <i>new</i> | 1 | \$ 60.00 | \$ 60.00 <i>+</i> |
| 3 | FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i> | 1 | \$ 30.00 | \$ 30.00 <i>+</i> |
| 4 | FRONT FENDER INNER GARNISH CLIP RH (SET) <i>new</i> | 1 | \$ 50.00 | \$ 50.00 <i>+</i> |
| 5 | FRONT FENDER INNER COWLING CLIP RH (SET) <i>new</i> | 1 | \$ 50.00 | \$ 50.00 <i>30</i> |
| 6 | WHEEL CAP (SET) <i>new</i> | 1 | \$ 150.00 | \$ 150.00 <i>+</i> |
| 7 | FRONT WHEEL RIM LH <i>let</i> | 1 | \$ 1,800.00 | \$ 1,800.00 <i>580</i> |
| 8 | FRONT WHEEL TYRE RH <i>new</i> | 1 | \$ 450.00 | \$ 450.00 <i>+</i> |
| 9 | BRAKE OIL <i>new</i> | 1 | \$ 40.00 | \$ 40.00 <i>+</i> |

540 TOTAL \$ 2,690.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

| S/N | JOB DESCRIPTION | PRICE | ADJUSTED COST |
|-----|---|-------------|---------------|
| 1 | PANEL BEATING, REMOVING AND REPLACING PARTS | \$ 1,400.00 | <i>500</i> |
| 2 | SPRAY PAINTING TO AFFECTED AREA | \$ 1,000.00 | <i>500</i> |
| 3 | TUFF COAT | \$ 250.00 | <i>30</i> |
| 4 | WIRING CHECK | \$ 120.00 | <i>30</i> |
| 5 | REMOVE AND REFIX FRONT UNDERCARRIAGE | \$ 650.00 | <i>200</i> |
| 6 | REMOVE AND REFIX POWER STEERING RACK AND PINION | \$ 350.00 | <i>+</i> |
| 7 | FOUR WHEEL ALIGNMENT | \$ 120.00 | <i>80</i> |
| 8 | RESET ABS LIGHT | \$ 350.00 | <i>+</i> |

TO : **MS FIRST CAPITAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SFX7391C**
 MODEL : **FIAT BRAVO**
 DATE OF ACCIDENT : 25.07.2022
 TIME OF ACCIDENT : 17:55HRS

| | | | |
|---|--|-----------|---|
| 9 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00 | x |
|---|--|-----------|---|

TOTAL \$ 7,220.00

1440

TOTAL PARTS COST : \$ 12,698.27
 TOTAL LABOUR COST : \$ 7,220.00
 TOTAL REPAIR COST : \$ 19,918.27

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Adrian L
 M/S 27/07/22

05 Pags.

total: 6661.63

c/s: 5.31c

5.31c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: