

Vehicle Damage Assessment Report for [SLR8078L]

Estimate Created: 27/07/2022 15:32 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 19/12/2022 00:24 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mitsubishi	Model	Lancer
Engine Type			
License Plate Number	SLR8078L	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$23,600.00 with 21 days for repair

Insurlogic 1 (19/12/2022 00:23)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear Bumper		1	881.40	-10.00 %	793.26
Rear Bumper Clips		1	30.00	0.00 %	30.00
Rear Bumper Screw Clips		1	20.00	0.00 %	20.00
Rear Bumper Reinforcement		1	234.00	-10.00 %	210.60
Rear Bumper Reflector RH & LH		1	84.00	-10.00 %	75.60
Rear Bumper Retainer RH & LH		1	90.00	-10.00 %	81.00
Rear Reverse Sensor		1	200.00	0.00 %	200.00
Rear End Panel		1	506.00	-10.00 %	455.40
Rear End Panel Retainer Middle		1	145.60	-10.00 %	131.04
Rear End Panel Inner Trim		1	166.00	-10.00 %	149.40
Rear End Panel Inner Trim Clips		1	16.00	0.00 %	16.00
Rear Taillamp RH & LH		1	716.00	-10.00 %	644.40
Rear Taillamp Panel RH & LH		1	390.00	-10.00 %	351.00
Rear Taillamp Seal RH & LH		1	40.00	0.00 %	40.00
Rear Boot Cover		1	899.00	-10.00 %	809.10
Rear Boot Cover Reflector Middle		1	235.00	-10.00 %	211.50
Rear Boot Cover Weatherstrip		1	274.40	-10.00 %	246.96
Rear Boot Cover Emblem		1	71.70	-10.00 %	64.53
Rear Boot Cover 'Lancer' Emblem		1	77.50	-10.00 %	69.75
Rear Boot Cover 'C&C' Emblem		1	67.75	-10.00 %	60.98
Rear Boot Cover Inner Trim		1	168.00	-10.00 %	151.20
Rear Boot Cover Inner Trim Clips		1	33.00	0.00 %	33.00
Rear Boot Cover Hinge RH & LH		1	264.60	-10.00 %	238.14
Rear Boot Cover Shock Absorber RH & LH		1	242.00	-10.00 %	217.80
Rear Boot Cover Spoiler		1	387.10	-10.00 %	348.39
Rear Boot Cover Lock (Upper)		1	291.60	-10.00 %	262.44
Rear Boot Cover Lock (Lower)		1	83.10	-10.00 %	74.79
Rear Boot Cover Reflector RH & LH		1	610.00	-10.00 %	549.00

Rear Boot Floor Panel	1	895.00	-10.00 %	805.50
Rear Boot Floor Panel Insulator	1	150.00	0.00 %	150.00
Rear Boot Floor Corner Panel RH	1	232.90	-10.00 %	209.61
Rear Spare Wheel Board	1	165.00	-10.00 %	148.50
Rear Fender RH & LH	1	1798.00	-10.00 %	1,618.20
Rear Fender Inner Trim RH & LH	1	484.00	-10.00 %	435.60
Rear Fender Inner Trim Clips RH & LH	1	48.00	0.00 %	48.00
Rear Windscreen Glass	1	1232.20	-10.00 %	1,108.98
Rear Windscreen Glass Moulding	1	210.00	-10.00 %	189.00
Rear Windscreen Glass Sealant	1	60.00	0.00 %	60.00
Rear Windscreen Glass Solar Film (3M)	1	250.00	0.00 %	250.00
Rear Number Plate 30 /	1	30.00	0.00 %	30.00
Rear Number Plate Bracket	1	29.00	0.00 %	29.00
Front Bumper	1	896.70	-10.00 %	807.03
Front Bumper Clips	10	3.00	0.00 %	30.00
Front Bumper Reinforcement	1	324.00	-10.00 %	291.60
Front Bumper Retainer RH & LH	1	95.00	-10.00 %	85.50
Front Bumper Under Cover	1	235.00	-10.00 %	211.50
Front Grille	1	285.00	-10.00 %	256.50
Front Emblem	1	71.70	-10.00 %	64.53
Front Grille Clips	6	3.00	0.00 %	18.00
Front Grille Seal	1	35.00	-10.00 %	31.50
Front Bonnet	1	899.70	-10.00 %	809.73
Front Bonnet Stand	1	90.00	-10.00 %	81.00
Front Bonnet Rubber Stopper RH & LH	4	20.00	-10.00 %	72.00
Front Bonnet Lock	1	95.00	-10.00 %	85.50
Front Bonnet Hinge RH & LH	2	60.00	-10.00 %	108.00
Front Headlamp RH & LH	2	948.40	-10.00 %	1,707.12
Front Fender RH	1	796.80	-10.00 %	717.12
Front Engine Mounting	4	202.60	-10.00 %	729.36
Front Engine Top Cover	1	280.50	-10.00 %	252.45
Front Engine Manifold	1	729.00	-10.00 %	656.10
Front Support Panel	1	582.00	-10.00 %	523.80
Front Support Panel Top Garnish	1	210.40	-10.00 %	189.36
Radiator	1	1228.80	-10.00 %	1,105.92

Radiator Bracket RH & LH	2	32.50	-10.00 %	58.50
Radiator Hose	1	45.00	-10.00 %	40.50
Aircon Condenser	1	1103.40	-10.00 %	993.06
Aircon Fan Assy	1	263.00	-10.00 %	236.70
Front Coolant Tank RH	1	240.50	-10.00 %	216.45
Front Fuse Box	1	160.70	-10.00 %	144.63
Battery	1	160.00	-10.00 %	144.00
Front Number Plate	1	30.00	0.00 %	30.00
Front Number Plate Bracket	1	29.00	0.00 %	29.00
Dash Cam	1	680.00	0.00 %	680.00

Parts Subtotal 23,024.13

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
To remove & refix the accident affected area	RnR	3200.00	0.00 %	3,200.00
RnR rear exhaust	RnR	80.00	0.00 %	80.00
RnR fuel tank	RnR	80.00	0.00 %	80.00
RnR rear windscreen	RnR	120.00	0.00 %	120.00
RnR rear upholstery	RnR	100.00	0.00 %	100.00
RnR rear reverse sensor	RnR	50.00	0.00 %	50.00
RnR aircon condense & top up gas	RnR	60.00	0.00 %	60.00
RnR radiator	RnR	60.00	0.00 %	60.00
To check fault code & resetting	RnR	120.00	0.00 %	120.00
To check wiring	RnR	60.00	0.00 %	60.00
Tuff-kote	RnR	100.00	0.00 %	100.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
To spray paint on the accident affected area	Full spray	2600.00	0.00 %	2,600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 4,030.00

Paint Labor Subtotal 2,600.00

Labor Subtotal 6,630.00

Summary

Repair Cost 29,654.13

Discount(20 %) (6,054.13)

23,600.00

Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	23,600.00