

Vehicle Damage Assessment Report for [SMX1559T]

Estimate Created: 27/07/2022 15:30 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 18/01/2023 16:29 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Prius
Engine Type			
License Plate Number	SMX1559T	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$3170.07 with 6 days for repair

Insurlogic 5 (18/01/2023 16:27)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
PANEL SUB ASSY REAR DOOR RH		1	1294.90	-25.00 %	971.18
TAPE BLACK OUT NO.1		1	21.90	-25.00 %	16.43
TAPE BLACK OUT. NO 2		1	24.90	-25.00 %	18.68
TAPE BLACK OUT NO 3		1	15.40	-25.00 %	11.55
PANEL SUB ASSY QTR LH		1	871.50	-25.00 %	653.63
HUB CAP		1	211.50	-25.00 %	158.63

Parts Subtotal 1,830.10

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
RUST PROOFING	RnR	60.00	0.00 %	60.00
RNR REAR INTERIOR	RnR	120.00	0.00 %	120.00
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	700.00	0.00 %	700.00
CHECK LIGHTING	RnR	20.00	0.00 %	20.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	440.00	0.00 %	440.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 900.00

Paint Labor Subtotal 440.00

Labor Subtotal 1,340.00

Summary

Repair Cost 3,170.10

Discount(0 %) (0.00)

3,170.10

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 3,170.10