Not Nothering Burny Burny

Trans-cab Auto Services Pte Ltd

LAD2205-010

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX1559T

	Vehicle No.: Chassis No.: Co UEN: Vehicle Make: Vehicle Model: Date of Accident: Third Party Insurer: Date of Registration:		SMX1559T JTDKB3FU8 201603575 TOYOTA PRIUS GEN 18/05/2022 GBH359A/ 29/12/2020	03091399 K 4 2
1	PANEL SLIP ASSV DEAD DOOD III			ST 1 294 90 —
1	THE TOTAL POOR LIT		Ψ	1,251.50
1	THE REPORT OF ENTING TRIVI, LA		\$	293.00 🗶
1	THE TOTAL POOR LOWER LA		\$	N 87.10 ✓
1	and the second of the second		\$	M 98.90 X
1	TAPE, BLACK OUT, NO.1 REAR LH TAPE, BLACK OUT, NO.2 REAR LH		\$	Ma 21.90 —
1			\$	na 34.90 -
1	TAPE, BLACK OUT, NO.3 REAR LH		\$	M 15.40 —
1	MOTOR ASSY, POWER WINDOW REGULATOR, LH		\$	926.00 🗶
	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH		\$	£ 206.70 ⊀
1 1	PANEL SUB-ASSY, QUARTER, LH		\$	By 871.50
	LINER, REAR WHEEL HOUSE, LH		\$	139.80 X
1	MOULDING ASSY, BODY ROCKER PANEL, LH		\$	594.80 X
1	HUB CAP		\$	nu 211.50 -
1	COVER SUB-ASSY, QUARTER PILLAR, LH		\$	207.30 X
1	RIM	_	\$	→ 1,900.10 X
		TOTAL		6,903.80
		25%	\$	1,725.95
			\$	5,177.85
Special Nett				
1	TYRE		¢	\$ 350.00 V
1	REAR BUMPER CLIP		\$	350.00 X
1	FENDER CLIP			65.00 X
1	FENDER LINER CLIP			Ma 130.00 X
1SET	DOOR TRIM CLIP			1~ 65.00 X
			\$	ル~ 70.00 人

Trans-cab Auto Services Pte Ltd LAD2205-010 No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G **SMX1559T** 1SET DOOR WEATHERSTRIP CLIP 130.00 X 1SET CLIP, ROCKER PANEL MOULDING 65.00 **X** TOTAL 875.00 **TOTAL PARTS \$** 6,052.85 **LABOUR** To Rust-Proofing and apply undercoat Of The Affected Areas. 240.00 601 To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. 380.00 /201 \$ Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same 1,600.00 7001 \$ To transfer of rear end panel fittings, attachment to facilitate bodywork repair. 2 380.00 X \$ Putty And Spray Painting Of The Affected Portion. 1,600.00 440/ \$ To reinstall rear bumper parking sensor. 170.00 X \$ To transfer of tire, rim and on wheel balancing. へ 170.00 To Check Electrical Lighting Concerned. \$ 170.00 201 To check steering geometry and computer wheel alignment nn 220.00 X To remove and refit of rear fender fitting LKK Auto Consultants hence notify the Repairer of the following: 170.00 X • To resurvey before/aliQspAlpainting 5,100.00 To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer

Signature:

Trans-cab Auto Services Pte Ltd

LAD2205-010

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX1559T

Over All Total \$ 11,152.85

(PART-BY-PART) Repair Days

20 days

6day,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 19/05/2022 15:53 (SGT) Date of Accident 18/05/2022 22:45 (SGT) **Exact Location of Accident** Lor 22 Geylang, Singapore Additional Location Information JUNCTION OF GUILLEMARD ROAD AND LOR 22 GEYLANG Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMX1559T

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner TRANS LEASING PTE LTD Company Reg No 2XXXXXXX75K **Email Address** Claims@transcab.com.sg Mobile Phone No (Phone) +65-65552222 Alternative Phone No. (Office) +65-65552222

VEHICLE PARTICULARS

Manufacturer Toyota Model **Prius** Variant Exact purpose for which vehicle was being used at time of accident Private hire

Are you claiming under your own insurance policy for repair to

your vehicle? No - Claiming third party Vehicle Category Private hire


Transmission Auto CC 1767

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd Type of Coverage ThirdParty Fleet Policy Yes **Policy Number** VFX/P2440417 Cover Note Number NA

DRIVER

Name of Driver HO BOON HENG NRIC No SXXXX955A





Police Station Of Origin: Geylang N.P.C 1 Cassia Link SINGAPORE 397618 Tel No: 1800-8486999 T/20220519/2060

Report No. T/20220510

Police

CONTINUATION OF REPORT

Driver HO BOON HENG				ID No. Contact No.		S7432955A
Name	e SMX1559T (Car)					
Related Vehicle						
Hospital/Clinic			INIC &	Class of Driving Licence & Expiry Date		Class: 3 Date of Explry: NIL
ate Treatment 19/05/2022 Date		Date Dis	210011111		/2022	
No. of Days granted Medical Leave 03			Degree	Degree of Injury Sligh		

Brief Details.

On 18/05/2022 at about 2245hrs, I was driving along Guillemard Road, towards Lorong 22 Geylang T-Junction, with 4 other passengers. I was at the 2nd lane of the said road, and wanting to turn left when the traffic light turns green for vehicles. When the traffic light turns green for vehicle to move, I turned less and subsequently the Lorry (GBH359A) on my left bumped onto the left side of my car. The lorry did not turn left as he was supposed to, in his lane. The lorry driver's lane is supposedly to turn left only, however the driver drove forward, which caused the accident.

I then sustained some pain on my neck and shoulder from the said accident. The passenger of the lorry then went down from the lorry and started scolding me. The lorry then drove straight and left the scene. The lorry driver did not stop to assist me or exchange particulars. I did not manage to get the particulars of the lorry driver however, my company (Transcab) managed to retrieved a lorry plate number which believed to be the said lorry. The passengers of the said lorry was still at scene and subsequently, the incident was attended by the police (G/20220518/0223).

On 19/05/2022 at about 1200hrs, I went to see a doctor at Our Family Physician Clinic & Surgery to check on my injury from the said incident. I was then given 3 days MC (19/05/2022 to 21/05/2022).

I then came to Geylang NPC to lodge a traffic accident report,