

Case Details

Case Reference Number : TAX/07/22/2084
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB660P

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-18908-ID
 Assigned By : Wei Siong #

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 25/07/2022 11:00 AM
 Vehicle Age(In Months) :-

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	de
Standard	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	? Xm
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	? Xm
Standard	Main			TAIL LAMP RH	1	557.80	557.80	25.00	418.35	Replace	1	418.35	Replace	cm
Total Spare Part Cost									938.10	Surveyor Total		762.30		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									750.48	Final Sur Total		609.84		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR BUMPER	676.00	200	
Total:			676.00	200.00 + 100 = 300	


Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			378.00	200.00 + 200 = 400	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK & RESET SYSTEM FUNCTION	50.00	0 <i>Yn</i>	
Total:			50.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	750.48	609.84
Total Labour Cost	676.00	200.00
Total Spray Painting	378.00	200.00
Other	50.00	0.00
Overall Total	1,854.48	1,009.84
Lump Sum Repair Option	☒	☒
Lump Sum Total	1,850.00	1,000.00
Surveyor Approved Amount		1,000.00
No of Repair Days*	3	2+2 = 4 days
Remarks	-	LUMP SUM REPAIR / RESURVEY AFTER PAINT .
Surveyor Name		Rasul
Signature		
		Save Clear
Survey Date	27/07/2022	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: