



**Section A - Accident Details**

Registration Number	SHB660P
Case Reference Number	TAX/07/22/2084
Registration Date	19/1/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	BINU BENJAMIN
Type of Accident	Head to Rear
Accident Date and Time	25/7/2022 7:00 PM
Accident Reported Date and Time	26/7/2022 12:19 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115723
Special Instruction to ARC, if any	OUR TAXI REAR PORTION BADLY DAMAGED/ BREAKLIGHT CRACKED/ BUMPER PULLED OUT
Prepared Date and Time	27/7/2022 11:07 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$976.00	\$300.00
Total Spray Cost	\$678.00	\$400.00
Total Spare Part Cost	\$1,197.07	\$1,021.28
Total Other Cost	\$50.00	(\$321.28)
<b>TOTAL COST</b>	<b>\$2,901.07</b>	<b>\$1,400.00 (L/S)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	<b>San Wei Lau</b>	<b>RASUL (LKK) / NTUC</b>
ARC / Surveyor Sign Off Date	<b>04/08/2022 3:37 PM</b>	<b>04/08/2022 2:42 PM</b>
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 2 days.	LUMP SUM REPAIR / RESURVEY AFTER PAINT .

**STRIDES Accident Vehicle Repair Estimates**

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/08/2022

User ID                      PohSuan

**Section C - Quotation and Accident Invoice Details**

Quotation Number	QN-2208-0162	Invoice Number	
Quotation Date	12.08.2022	Invoice Date	
Invoice Amount		Prepared Date	

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR BUMPER	\$676.00	\$200.00
TO REPAIR REAR END PANEL	\$300.00	\$100.00
<b>Total Labour</b>	<b>\$976.00</b>	<b>\$300.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$300.00	\$200.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$678.00</b>	<b>\$400.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK & RESET SYSTEM FUNCTION	\$50.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$321.28)
<b>Total Other Costs</b>	<b>\$50.00</b>	<b>(\$321.28)</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6505548		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		81551-47180	TAIL LAMP RH	1.00	\$557.80	25.00	\$418.35	Replace	Replace
<b>Total</b>					<b>\$1,250.80</b>		<b>\$762.30</b>		

 ✓  
X  
X  
✓

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
<b>Total</b>					<b>345.30</b>		<b>258.98</b>		

 ✓  
✓

	1,021.28	
+	300.00	
+	400.00	L/S \$1,400/-
	1,721.28	
	-20%	
	1,377.02	