

Munich Autocare Pte Ltd

60 Jalan Lam Huat, #07-43
Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

Repairer Estimates

Kenneth

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	26/07/2022
Vehicle Reg. No.:	SMJ1610B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	OPEL INSIGNIA GRANDSPORT	Vehicle Reg. Date:	25/02/2019
Vehicle Colour:	B16DTH, 1.6 TURBO (A)		
Engine No:	RED	Chassis No:	W0VZM6EF8K1034539
Odometer:	A2183178JSUX0332		
	258421 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	<i>54</i>		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

NOT WITHDRAWN
Money After Claim
Ex @ 2000/-
11 Bmp @ 3450/-

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	9,358.80
Labour	84.00
Paintwork Labour	2,440.00
Towing	0.00
	0.00
Calculated Gross Total (S\$)	11,882.80
- Excess (S\$)	2,000.00
(S\$)	9,882.80
+ GST 7.00% (S\$)	691.80
Nett Amount (S\$)	10,574.60

his claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jul 2022)
 Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Munich Autocare Pte Ltd/SMJ1610B/27/07/2022 16:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39214206	*FRONT BONNET	R	0.00	*1,705.00 F X
2	1	39118540	*FRONT BONNET LOCK	R	0.00	*43.00 F X
3	1	39143307	*FRONT BONNET LOCK BRACKET	R	0.00	*127.00 F X
4	1	39114984	*FRONT RADIATOR GRILLE TOP GARNISH	in	0.00	*40.00 F X
5	1	39197502	*FRONT RADIATOR TOP INNER GARNISH	in	0.00	*141.00 F
6	1	39107929	*RADIATOR GRILLE	cm	0.00	*384.00 F
7	1	13491196	*RADIATOR GRILLE MOULDING (CHROME)	cm	0.00	*391.00 F
8	1	13491204	*FRONT LOGO EMBLEM	in	0.00	*75.00 F
9	1	39210099	*FRONT HEADLAMP LH	cm	0.00	*1,055.00 F X
10	1	39210100	*FRONT HEADLAMP LR 1655	cm	0.00	*1,055.00 F
11	1	13491383	*FRONT HEADLAMP LOWER BRACKET LH	in	0.00	*60.00 F X
12	1	13491381	*FRONT HEADLAMP LOWER BRACKET RH	in	0.00	*60.00 F X
13	1	39108221	*FRONT BUMPER LOWER GRILLE	R	0.00	*120.00 F X
14	1	39159651	*FRONT BUMPER 1158	in	0.00	*1,158.00 F
15	1	1349119013491191	*FRONT RADIATOR GRILLE MOULDING LH/RH (CHROME)	cm	0.00	*270.00 F X
16	1	39098178	*FRONT BUMPER SPONGE	cm	0.00	*107.00 F
17	1	39117745	*FRONT BUMPER REINFORCEMENT 459	R	0.00	*459.00 F
18	1	39108219	*FRONT BUMPER LOWER LIP GARNISH LH	in	0.00	*65.00 F X
19	1	39108220	*FRONT BUMPER LOWER LIP GARNISH RH	in	0.00	*65.00 F X
20	1	39020290	*FRONT BUMPER MOULDING RH	in	0.00	*70.00 F X
21	1	39020289	*FRONT BUMPER MOULDING LH	in	0.00	*70.00 F X
22	1	39143306	*FRONT SUPPORT PANEL	R	0.00	*258.00 F X
23	1	39077621	*FRONT UPPER SUPPORT PANEL	R	0.00	*170.00 F X
24	1	95515167	*FRONT PARKING SENSOR	in	0.00	*410.00 F
25	1	13238718	*FRONT BUMPER SENSOR HARNESS WIRE	in	0.00	*150.00 F

F=Franchise part.

Sub Total (S\$) 8,508.00
 + Margin on L,N Items 10.00% (S\$) 850.80
Total Parts (S\$) 9,358.80

Munich Autocare Pte Ltd/SMJ1610B/27/07/2022 16:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 9:41 AM

1-32-C6Z5

Estimates on Miscellaneous Items

Repairer Estimates

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIPS	42.00
2	1	FRONT RADIATOR TOP GARNISH CLIPS	42.00
Sub Total (\$\$)			84.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET, BUMPER, SUPPORT PANEL, CHASSIS LH/RH AND ALL DAMAGE AREAS	New	3501 1,200.00
2	TO CHECK ALL WIRING FOR PROPER FUNCTION AND PARKING SENSOR FOR OPERATION	New	501 120.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH, FOG LAMP LH/RH FOCUS	New	201 120.00
4	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER, FRONT BUMPER, SUPPORT PANEL, AND POLISH ALL DAMAGE AREAS	New	4001 1,000.00
Gross Labour Cost (\$\$)			2,440.00

Munich Autocare Pte Ltd/SMJ1610B/27/07/2022 16:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >