

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

Kenneth

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	26/07/2022
Vehicle Reg. No.:	SMJ1610B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 TURBO (A)	Vehicle Reg. Date:	25/02/2019
Vehicle Colour:	RED	Chassis No:	W0VZM6EF8K1034539
Engine No:	A2183178JSUX0332		
Odometer:	258421 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	54		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

*NOT Withheld
Running After Police
7 days
Ex 82000.*

COST OF CLAIMS

	Amount
Parts	9,358.80
Miscellaneous Items	84.00
Labour	2,440.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	11,882.80
- Excess (S\$)	2,000.00
(S\$)	9,882.80
+ GST 7.00% (S\$)	691.80
Nett Amount (S\$)	10,574.60

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jul 2022)
Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Munich Autocare Pte Ltd/SMJ1610B/27/07/2022 16:50
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39214206	*FRONT BONNET	R	0.00	0.00 *1,705.00 F X
2	1	39118540	*FRONT BONNET LOCK	R	0.00	0.00 *43.00 F X
3	1	39143307	*FRONT BONNET LOCK BRACKET	R	0.00	0.00 *127.00 F X
4	1	39114984	*FRONT RADIATOR GRILLE TOP GARNISH	1/2	0.00	0.00 *40.00 F X
5	1	39197502	*FRONT RADIATOR TOP INNER GARNISH	0/1	0.00	0.00 *141.00 F C
6	1	39107929	*RADIATOR GRILLE	CM	0.00	0.00 *384.00 F C
7	1	13491196	*RADIATOR GRILLE MOULDING (CHROME)	CM	0.00	0.00 *391.00 F C
8	1	13491204	*FRONT LOGO EMBLEM	R	0.00	0.00 *75.00 F C
9	1	39210099	*FRONT HEADLAMP LH	BA	0.00	0.00 *1,055.00 F X
10	1	39210100	*FRONT HEADLAMP LR	CM	0.00	0.00 *1,055.00 F C
11	1	13491383	*FRONT HEADLAMP LOWER BRACKET LH	1/2	0.00	0.00 *60.00 F X
12	1	13491381	*FRONT HEADLAMP LOWER BRACKET RH		0.00	0.00 *60.00 F 7
13	1	39108221	*FRONT BUMPER LOWER GRILLE	1/2	0.00	0.00 *120.00 F X
14	1	39159651	*FRONT BUMPER	CM	0.00	0.00 *1,158.00 F C
15	1	1349119013491191	*FRONT RADIATOR GRILLE MOULDING LH/RH (CHROME)	di?	0.00	0.00 *270.00 F
16	1	39098178	*FRONT BUMPER SPONGE	CM	0.00	0.00 *107.00 F C
17	1	39117745	*FRONT BUMPER REINFORCEMENT	R	0.00	0.00 *459.00 F C
18	1	39108219	*FRONT BUMPER LOWER LIP GARNISH LH	1/2	0.00	0.00 *65.00 F X
19	1	39108220	*FRONT BUMPER LOWER LIP GARNISH RH	1/2	0.00	0.00 *65.00 F X
20	1	39020290	*FRONT BUMPER MOULDING RH	1/2	0.00	0.00 *70.00 F X
21	1	39020289	*FRONT BUMPER MOULDING LH	1/2	0.00	0.00 *70.00 F X
22	1	39143306	*FRONT SUPPORT PANEL	R	0.00	0.00 *258.00 F X
23	1	39077621	*FRONT UPPER SUPPORT PANEL	R	0.00	0.00 *170.00 F X
24	1	95515167	*FRONT PARKING SENSOR		0.00	0.00 *410.00 F Z
25	1	13238718	*FRONT BUMPER SENSOR HARNESS WIRE		0.00	0.00 *150.00 F Z

F=Franchise part.

Sub Total (S\$) 8,508.00
+ Margin on L,N Items 10.00% (S\$) 850.80
Total Parts (S\$) 9,358.80

Munich Autocare Pte Ltd/SMJ1610B/27/07/2022 16:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT BUMPER CLIPS	<i>Ne</i>	42.00	<i>-</i>
2	1	FRONT RADIATOR TOP GARNISH CLIPS	<i>Ne</i>	42.00	<i>-</i>
Sub Total (\$\$)				84.00	

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER, SUPPORT PANEL ,CHASSIS LH/RH AND ALL DAMAGE AREAS	New	<i>3501</i>	1,200.00
2	TO CHECK ALL WIRING FOR PROPER FUNCTION AND PARKING SENSOR FOR OPERATION	New	<i>501</i>	120.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH , FOG LAMP LH/RH FOCUS	New	<i>201</i>	120.00
4	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER , FRONT BUMPER, SUPPORT PANEL , AND POLISH ALL DAMAGE AREAS	New	<i>4001</i>	1,000.00

Gross Labour Cost (\$\$)**2,440.00**

Munich Autocare Pte Ltd/SMJ1610B/27/07/2022 16:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >