



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0627/2022/EQ
DATE : 27-Jul-22
WIP : 34767

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/7/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. RISHAB MUKHERJEE
ADDRESS : 5 PEMIMPIN DRIVE
#16-04, SEASONS VIEW
SINGAPORE 576149
TELEPHONE : HP +65 81276956
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100462077-06
VEHICLE NO : SLB 9706 K
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S-TRONIC
MODEL YEAR : 27/4/2016
ENGINE NO : CVN 006626
CHASSIS NO : WAUZZZF41GA048197
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jul-22
PLACE OF ACCIDENT : NORTH BUONA VISTA ROAD & COMMONWEALTH AVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 9706 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250 /	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 /	
4	TO REMOVE AND REINSTALL LHS AND RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS AND RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR.	S/N \$ 560.00 /	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR, LHS FRONT FENDER TOP SUPPORT AND LHS UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,000.00 3000 / 6 x 500	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER, LHS FRONT FENDER TOP SUPPORT, LHS X UPPER A-PILLAR AND LHS FRONT DOOR.	\$ 5,000.00 3025 /	
SUB-TOTAL LABOUR CHARGES		\$ 13,790.00	

55 x 550

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 9706 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT PRE WHEEL ALIGNMENT.	S/N \$ 240.00	X
8	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.	S/N \$ 280.00	/
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 14,694.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 9706 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER / <i>OR</i>	1	\$ 2,377.00	1901.60	
2	FRONT BUMPER FIXING PARTS / <i>MC</i>	1	\$ 612.00	489.60	
3	FRONT BUMPER SECURING STRIP / <i>OR</i>	1 <i>X</i>	\$ 79.00	31.60	
4	FRONT BUMPER GRILLE - CENTER ? <i>X</i> <i>nn</i>	1	\$ 219.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE / <i>CR</i>	1	\$ 254.00	203.20	
6	FRONT BUMPER AIR GUIDE - LH / <i>OR</i>	1	\$ 72.00	57.20	
7	RADIATOR GRILLE / <i>OR</i>	1	\$ 1,277.00	1021.60	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / <i>mis</i>	1	\$ 151.00	120.40	
9	FRONT BUMPER FOAM FILLER PIECE / <i>OR</i>	1	\$ 139.00	110.80	
10	FRONT REINFORCEMENT BEAM / <i>BT</i>	1	\$ 899.00	719.20	
11	FRONT BUMPER GUIDE SECTION - LH / <i>OR</i>	1	\$ 41.00	32.24	
12	FRONT BUMPER TOP COVER / <i>OR</i>	1	\$ 143.00	114.00	
13	SIGN 'CAUTION' STICKER / <i>MC</i>	1	\$ 16.00	12.40	
14	STICKER FOR AIR CONDITIONER / <i>MC</i>	1	\$ 9.00	6.64	
15	FRONT REINFORCEMENT BEAM BRACKET - LH ? / <i>BT</i>	1	\$ 254.00	203.20	
16	FRONT LOCK CARRIER BRACKET / <i>OR</i>	1	\$ 154.00	122.80	
17	FRONT BUMPER SUPPORT - LH/RH / <i>MC</i>	2	\$ 64.00	51.04	
18	POP RIVET / <i>MC</i>	4	\$ 4.00	2.88	
19	HORN - LH ? <i>X</i> <i>nn</i>	1	\$ 134.00		
20	HORN BRACKET - LH ? <i>X</i> <i>nn</i>	1	\$ 33.00		
			\$ 6,931.00		

SUB TOTAL SPARE PARTS

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 9706 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER - LH / <i>DN</i>	1	\$	861.00 /	688.80
22	FENDER ATTACHMENT PART X <i>nn</i>	1	\$	211.00	
23	FRONT FENDER CLOSING ELEMENT - LH / <i>Mc</i>	1	\$	81.00 /	64.24
24	FRONT FENDER BRACKET - LH FRONT / <i>BT</i>	1	\$	41.00 /	32.72
25	FRONT FENDER BRACE - LH / <i>BT</i>	1	\$	132.00 /	105.20
26	FRONT FENDER BRACKET - LH / <i>BT</i>	1	\$	55.00 /	44
27	FRONT FENDER BRACKET - LH CENTER / <i>BT</i>	1	\$	36.00 /	28.08
28	FRONT FENDER CLOSING ELEMENT - LH REAR ? X <i>nn</i>	1	\$	37.00	
29	FRONT FENDER SIDE COVER - LH X <i>nn</i>	1	\$	13.00	
30	FRONT FENDER POP RIVET / <i>Mc</i>	7	\$	27.00 /	21.28
31	FRONT WHEEL HOUSING LINER - LH / <i>CR4</i>	1	\$	260.00 /	208
32	WHEEL HOUSING LINER ATTACHEMENT PART / <i>Mc</i>	1	\$	219.00	
33	FRONT WHEEL SPOILER - LH / <i>BR</i>	1	\$	82.00 /	65.12
34	FRONT WHEEL SPOILER TRIM - LH X <i>nn</i>	1	\$	39.00	
35	FRONT FENDER STONE CHIP GUARD - LH / <i>Mc</i>	1	\$	57.00 /	45.28
36	FRONT FENDER LEDGE COVER - FRONT / <i>MS</i>	1	\$	35.00 /	27.52
37	FRONT FENDER LEDGE COVER - LH OUTER / <i>CR4</i>	1	\$	26.00 /	20.16
38	BONNET / <i>DN</i>	1	\$	3,425.00 /	2740
39	BONNET ATTACHMENT PART X <i>nn</i>	1	\$	431.00	
40	BONNET HINGE - LH/RH ? X <i>nn</i>	2	\$	680.00	
SUB TOTAL SPARE PARTS			:	\$	6,748.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 9706 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET IMPACT PROTECTION - CENTER / LH / RH / <i>npc</i>	3	\$ 93.00	73.20
42	BONNET HINGE COVER <i>X hn</i>	1	\$ 68.00	
43	BONNET GAS FILLED STRUT <i>X nn</i>	2	\$ 512.00	
44	BONNET STRIKER <i>/ BT</i>	1	\$ 56.00	44.56
45	BONNET LOCK <i>/ BT</i>	1	\$ 228.00	182.00
46	BONNET BOWDEN CABLE <i>? X nn</i>	1	\$ 64.00	
47	BONNET BOWDEN CABLE COVER <i>? X nn</i>	1	\$ 11.00	
48	BONNET BOWDEN CABLE <i>? X nn</i>	1	\$ 64.00	
49	BONNET RELEASE LEVER <i>? X nn</i>	1	\$ 15.00	
50	BONNET LOCK CABLE <i>? X nn</i>	1	\$ 82.00	
51	PLENUM CHAMBER COVER <i>X nn</i>	1	\$ 108.00	
52	BONNET SOUND ABSORBER <i>/ CRV</i>	1	\$ 382.00	305.60
53	LED HEADLIGHT - LH <i>/ BR</i>	1	\$ 8,294.00	6635.20
54	HEADLIGHT POWER MODULE <i>/ BR</i>	1	\$ 840.00	673.60
55	HEADLIGHT CONTROL UNIT <i>/ BR</i>	1	\$ 840.00	672.00
56	HEADLIGHT HOSE - LH <i>/ CRV</i>	1	\$ 42.00	32.88
57	HEADLIGHT COMPENSATION PIECE <i>/ BT</i>	3	\$ 135.00	108.00
58	HEADLIGHT WASH CYLINDER - LH <i>/ BR</i>	1	\$ 231.00	184.40
59	HEADLIGHT WASH CYLINDER BRACKET - LH <i>/ MC</i>	1	\$ 7.00	5.44
60	WASHER HOSE <i>? X nn</i>	1	\$ 107.00	
SUB TOTAL SPARE PARTS			\$ 12,179.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 9706 K

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT LOCK CARRIER <i>GR</i>	1	\$ 1,127.00	<i>901.60</i>
62	RADIATOR SUPPORT - LH/RH <i>X nn</i>	2	\$ 86.00	
63	A/C CONDENSER <i>X nn</i>	1	\$ 683.00	
64	REFRIGERANT LINE <i>X nn</i>	1	\$ 186.00	
65	REFRIGERANT LINE <i>X nn</i>	1	\$ 381.00	
66	REFRIGERANT LINE <i>X nn</i>	1	\$ 277.00	
67	BOLT <i>X nn</i>	1	\$ 3.00	
68	REFRIGERANT PIPE <i>BT</i>	1	\$ 585.00	<i>468.00</i>
69	REFRIGERANT PIPE BRACKET <i>mc</i>	1	\$ 9.00	<i>6.48</i>
70	REFRIGERANT PIPE BRACKET <i>mc</i>	1	\$ 21.00	<i>16.32</i>
71	RADIATOR <i>X nn</i>	1	\$ 699.00	
72	ADDITIONAL RADIATOR <i>X nn</i>	1	\$ 545.00	
73	FAN RING <i>X nn</i>	1	\$ 291.00	
74	RADIATOR FAN WITH CONTROL UNIT <i>X nn</i>	1	\$ 2,483.00	
75	RADIATOR AIR GUIDE - LH <i>X nn</i>	1	\$ 32.00	
76	RADIATOR AIR GUIDE - LH/RH UPPER <i>X nn</i>	2	\$ 28.00	
77	RADIATOR AIR GUIDE - UPPER <i>X nn</i>	1	\$ 19.00	
78	RADIATOR AIR GUIDE - LOWER <i>X nn</i>	1	\$ 25.00	
79	COOLANT <i>mc</i>	6	\$ 282.00	<i>237.12</i>
80	FRONT DOOR WINDOW SLOT SEAL - LH <i>X nn</i>	1	\$ 344.00	
		:	\$ 8,106.00	

SUB TOTAL SPARE PARTS

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 9706 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
81	WINDSCREEN WATER DEFLECTOR - LH X nn	1	\$ 75.00		
82	FRONT DOOR WINDOW TRIM STRIP - LH X nn	1	\$ 287.00		
83	INTAKE AIR DUCT X nn	1	\$ 25.00		
84	INTAKE AIR GUIDE X nn	1	\$ 61.00		
85	INTAKE HOSE X nn	1	\$ 110.00		
86	AIR FILTER X nn	1	\$ 418.00		
87	FRONT NO. PLATE / m	S/N	\$ 60.00	✓	
88	SUNDRIES ? / REC		\$ 500.00	13.20	
TOTAL SPARE PARTS			:	\$ 35,500.00	
TOTAL LABOUR CHARGES			:	\$ 14,694.00	
GRAND TOTAL			:	\$ 50,194.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
28/7/12, 11.00h

00-LAL
Excess?

PIP
M B L Y
17 45

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Paint prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- Third party survey (s) is allowed
- Third party survey (s) must be resurveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT