

ASS. REC. BY: Tough

REF:

CS / TMI 22007211 / Trv3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Lim TS

Veh No: SHA / 8109Yr Regn: 249, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HyundaiC.C. 1580Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 398557

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLC851CMV4/145741

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westerbe

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 29/7/22Survey held at Comfort Logy

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / I.B.L. (P) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

UP/P)
LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/07/2022
Vehicle Reg. No.:	SHA1810Y	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	03/05/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU210457	Chassis No:	KMHC851CVKU145741
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	3,207.28
Miscellaneous Items	11.00
Labour	1,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,798.28
+ GST 7.00% (\$\$)	335.88
Nett Amount (\$\$)	5,134.16

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Jul 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA1810Y/28/07/2022 15:59**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	de ✓ *459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	ov ✓ *451.25 FL
3	1		*REAR BUMPER LOWER MOULDING	20.00	0.00	x ✓ *155.00 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	x ✓ *394.80 FL
5	1		*REAR BUMPER SIDE BRKT LH	20.00	0.00	de ✓ *55.80 FL
6	10		*REAR BUMPER CLIPS	20.00	0.00	rel ✓ *22.00 FL
7	1		*REAR BUMPER REFLECTOR LH	20.00	0.00	int ✓ *41.45 FL
8	1		*REAR FENDER LH	20.00	0.00	Rp ✓ *1,768.30 FL
9	1		*REAR FENDER SHIELD LH	20.00	0.00	✓ *73.60 FL
10	1		*REVERSE SENSORS	0.00	0.00	'x ✓ *180.00 F
11	1		*REAR BUMPER MAT	0.00	0.00	rel ✓ *50.00 F
12	2		*REAR FENDER ADV.STICKER RH/LH	0.00	0.00	rel ✓ *200.00 F
13	1		*REAR FENDER (PETROL ONLY) LH	0.00	0.00	rel ✓ *40.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **3,891.60**- List Item Discount on L Items (S\$) **684.32**Total Parts (S\$) **3,207.28**

ComfortDelGro Engineering Pte Ltd/SHA1810Y/28/07/2022 15:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700 800.00
2	SPRAY PAINTING	New	500 600.00
3	TUFF KOTE	New	30 60.00
4	R/I REVERSE SENSORS	New	30 120.00
Gross Labour Cost (S\$)			1,580.00

ComfortDelGro Engineering Pte Ltd/SHA1810Y/28/07/2022 15:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495747
wp, 21/7/22 @ 3pm
c/s Resurvey after repair
Tanpin @ 16 parts work
= 3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tel: 1762 6687

28 JUL 2022

Recommendation	28 JUL 2022
----------------	-------------

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 28.07.2022 15:10

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4474389

JC N05524867

STOMER

MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

COUNT CARD NO.

Merimen

REGN NO.:
SHA1810Y

MILEAGE

MAKE:
HYUNDAI

FUEL

E.....1/2.....F

MODEL
IONIQ(G2)DATE/TIME IN
27.07.2022 18:20YR OF MANU.
03.05.2019

TARGET DATE

CHASSIS CODE
KMHC851CVKU145741

COMPLETION DATE/TIME:

JOB DESCRIPTION

LS

SMK


8733D

Rent Date: 27.07.2022

RE: 3P 27.07.2022

LABOR CODE
PBDESCRIPTION
PANEL BEATING-SHA1810Y-TP

TAKE PHOTOGRAPH
BEFORE / AFTER
SPRAY PAINTING



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHA1810Y

LIMITS

Vehicle No.:
SHA1810Y

Service Advisor

Signature/Date

Name of Service Advisor

Date