



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22007217/Kqy3q2 Date: 09/09/2022	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLX 8706B	Veh. Inspected	GBH 7256S	
Policy No.	P10524019R01	Coverage (\$)	0.00	
Claim No.	C10016583/JM	Excess (\$)	0.00	
Assign From	SALIZAWATI	Assign Date	28/07/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN CADDY (A)	c.c	1968	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WV1ZZZ2KZHX163143	Colour	WHITE	
Odometer	60937 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	CONTINENTAL	8 mm	
L/H Front Tyre	195/65 R15	CONTINENTAL	8 mm	
R/H Rear Tyre	195/65 R15	CONTINENTAL	8 mm	
L/H Rear Tyre	195/65 R15	CONTINENTAL	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/07/2022	Inspection Date	29/07/2022	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	