



TRANS EUROKARS PTE LTD

27A TANJONG PENJURU, SINGAPORE 609042

ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME :		WIP :		28687	
3 ANSON ROAD		ADDRESS :		DATE:		27-Jul-22	
#16-00 SPRINGLEAF TOWER							
SINGAPORE 079909		TEL :					
ATTN : MOTOR CLAIMS							

VEH NO :	SGC6936L	DATE IN :		CONTACT PERSON :	JESS
CHASSIS NO :	JM6KE1032G0313542	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	CX-5	DATE REG.:	19-May-15		

NATURE OF WORKS								
NO	DESCRIPTION	QTY	UNIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER KE	1	1,278.90			MKDY3-50-22XFBB	cul	1,278.90
2	RETAINER S.S ULTRASONIC CENTER	2	10.20			MKD49-67-UC5A	nec	20.40
3	PAD, PROTECTOR	5	7.80			MG001-67-061	nec	39.00
4	RETAINER S.S ULTRASONIC SIDE	2	15.50			MKD45-67-UC5A85		31.00
5	SENSOR ULTRASONIC SIDE	2	180.90			MGMK6-67-UC1 85		361.80
6	SENSOR ULTRASONIC CENTER	2	202.60			MKD49-67-UC1		405.20
7	REINFORCEMENT REAR	1	520.00			MKD53-50-260D	DD	520.00
8	STAY REAR BUMPER	2	17.30			MKD53-52-B22A	nec	34.60
9	BRACKET CENTER REAR BUMPER	1	5.40			MDFR5-50-251	nec	5.40
10	GROMMET, SCREW	6	2.70			MBHN1-50-0Z1A	nec	16.20
11	TAPE PROTECTOR	2	7.60			MBR5S-56-994	nec	15.20
12	REFLECTOR LH	1	106.30			MKD31-51-5M0	svc	106.30
13	REFLECTOR RH	1	106.30			MKD31-51-5L0	svc	106.30
14	COVER RH TOWING HOOK	1	2.70			MKD53-50-EK1A	mis	2.70
15	COVER LH TOWING HOOK	1	2.70			MKD53-50-EL1A	mis	2.70
16	FASTENER	2	3.00			MB45A-56-146A	nec	6.00
17	RETAINER RH REAR BUMPER	1	34.10			MKD53-50-2H1A	nec	34.10
18	RETAINER LH REAR BUMPER	1	34.10			MKD53-50-2J1A	nec	34.10
19	GASKET RH LAMP TRUNK LID	1	45.90			MKD53-51-3H8B	svc	45.90
20	GASKET LH LAMP TRUNK LID	1	45.90			MKD53-51-3J8B	svc	45.90
21	GASKET RH TAIL LAMP	1	37.00			MKD54-51-153B	nec	37.00
22	GASKET LH TAIL LAMP	1	37.00			MKD54-51-163B	nec	37.00
23	ORNAMENT CX-5	1	47.60			MKD53-51-721	svc	47.60
24	ORNAMENT SKYACTIV	1	75.20			MKD53-51-771	svc	75.20
25	MASCOT REAR	1	54.30			MKD53-51-731	svc	54.30
26	CLIP	3	5.70			MEG21-51-SJ3	svc	17.10

SUPPLEMENTARY								
NO	DESCRIPTION	QTY	UNIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES
1								

		TOTAL PARTS		3,379.90
		TOTAL PARTS COST		3,379.90
	<u>Labour Description</u>			
			REVISED	PRICES
1		TO REPLACE REAR BUMPER AND REPAIR TAILGATE.	660 /	1,500.00
2		TO RESPRAY REAR BUMPER AND TAILGATE.	630 /	1,400.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	330 /	660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 /	250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180 /	300.00
6	MZ-BR-SUNDRI	SUNDRIES.	10 20	50.00
	<u>SUPPLEMENTARY LABOUR DESCRIPTION</u>			
1		#N/A		
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.		TOTAL LABOUR	-	4,160.00
		TOTAL PARTS	-	3,379.90
		TOTAL	-	7,539.90
		LESS EXCESS	-	-
		TOTAL AFTER EXCESS	-	-
		GST 7%	-	-
		GRAND TOTAL	-	-

TRANS EUROKARS PTE LTD

Thuan@lkhauto.com

82235469

1/8/22 1600

3 days wp

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer