

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0629/2022/TF
DATE : 27-Jul-22
WIP : 34744

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/7/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS. ZAWIYAH BINTE MOHAMED ZAIN
ADDRESS : 23 SEA BREEZE ROAD
SINGAPORE 487454
TELEPHONE : HP +65 97535152
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900236767-01
VEHICLE NO : **SMQ 1698 L**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S-TRONIC
MODEL YEAR : 31/10/2019
ENGINE NO : DLH 066959
CHASSIS NO : WAUZZZF2XLN013689
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jul-22
PLACE OF ACCIDENT : INTERSECTION OF JALAN ANGIN LAUT
AND SIMEI AVENUE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 1698 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR.	S/N \$ 280.00 X	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,400.00 1000	
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR. ✓	\$ 3,000.00 1100	
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 7240 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 3,012.00	✓
2	FRONT BUMPER FIXING PARTS <i>HE m</i>	1	\$ 658.00	+
3	FRONT RADIATOR GRILLE CLOSING ELEMENT <i>HE m</i>	1	\$ 248.00	+
4	FRONT BUMPER SIDE REINFORCEMENT - RH <i>HE m</i>	1	\$ 44.00	+
5	FRONT BUMPER LOWER GRILLE - CENTRE <i>HE m</i>	1	\$ 125.00	+
6	FRONT BUMPER CLOSING ELEMENT - LOWER ?	1	\$ 171.00	?
7	FRONT BUMPER SPOILER	1	\$ 235.00	
8	FRONT BUMPER AIR GRILLE - RH <i>HE m</i>	1	\$ 485.00	+
9	FRONT BUMPER AIR GUIDE - RH <i>HE m</i>	2	\$ 57.00	+
10	FRONT BUMPER GUIDE SECTION - RH ?	1	\$ 50.00	?
11	FRONT BUMPER BRACKET - RH ?	1	\$ 61.00	?
12	FRONT BUMPER TOP COVER <i>HE m</i>	1	\$ 140.00	+
13	FRONT BUMPER REINFORCEMENT FOAM <i>HE m</i>	1	\$ 252.00	+
14	FRONT BUMPER REINFORCEMENT <i>HE m</i>	1	\$ 1,076.00	+
15	FRONT BUMPER SUPPORT ?	1	\$ 67.00	?
16	RIVET <i>HE m</i>	1	\$ 6.00	✓
17	CAUTION STICKER <i>HE m</i>	1	\$ 16.00	+
18	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,649.00	✓
19	FRONT FENDER ATTACHMENT PARTS <i>HE m</i>	1	\$ 44.00	+
20	FRONT FENDER BRACE - RH ?	1	\$ 137.00	?
SUB TOTAL SPARE PARTS		:	\$ 8,533.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 7240 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - UPPER ?	1	\$ 49.00	?
22	FRONT HEADLIGHT - RH <i>at</i>		\$ 9,172.00	✓
23	FRONT NO PLATE <i>hem</i>	S/N	\$ 60.00	X
24	SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 18,114.00	
TOTAL LABOUR CHARGES		:	\$ 6,752.00	
GRAND TOTAL		:	\$ 24,866.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *28/07/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT