

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 01 Aug 2022

Preliminary Advice

Vehicle No	: GBL1756J	Accident Date	: 23/07/2022
Make	: TOYOTA HIACE	Policy No.	: SPMF100000537
Assignment Date	: 29/07/2022	Excess	: S\$1,300.00
Date of Inspection	: 29/07/2022	Est. Duration of Repair	: 20
Inspection At	: CITY AUTO PTE LTD (HQ) 160 SIN MING DRIVE #05-01,, SIN MING AUTOCITY, SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 22,304.00
Revised Amount	:S\$ 12,774.70
Check Items (Estimated)	:S\$ 6,768.30
Total	:S\$ 19,543.00
Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 85,000.00
COE / PARF Rebate	:S\$ 27,187.00
Salvage Value	:S\$

Margin for Repair

:S\$ 57,813.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO THE VEHICLE USED LESS THAN 3 YEARS.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.