

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007236/UPA3Q2**Date:** 02/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210044251
Claimant Vehicle No :	SMT6211J	Insured Vehicle No :	SNA3123M
Date of Loss:	24/07/2022	Nature of Claim:	TP
		Claim No:	9813408712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT6211J		
Make & Model:	MERCEDES-BENZ C180, 1.6 Kompressor (A)	Engine No:	27191031353350
Reg. Date:	09/05/2012 (Man. Year: 2012)	Chassis No:	WDD2040452A688623
Colour:	White/Yellow	Odometer:	157091 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,085.20	2,798.60	4,286.60	60.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,390.00	970.00	1,420.00	59.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,475.20	3,768.60	5,706.60	60.23
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	9,475.20	3,000.00	6,475.20	68.34
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		3,278.45		

INSPECTION

Date of Assignment:	29/07/2022	
Date Inspected:	29/07/2022 Inspected At:	Ping Motor Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-25 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,259.00 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	116.00 FL	*- FL
3	1		*FRONT BUMPER LOWER LIP	Cut	1,118.00 FL	*1,118.00 FL
4	1		*FRONT FENDER LH	Repair	876.00 FL	*- FL
5	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	232.00 FL	*- FL
6	1		*FRONT ABSORBER LH	Not Necessary	697.00 FL	*- FL
7	1		*FRONT LOWER ARM LH	Not Necessary	527.00 FL	*- FL
8	1		*FRONT KNUCKLE ARM LH	Warped	780.00 FL	*780.00 FL
9	1		*FRONT KNUCKLE BEARING LH	Necessary	156.00 FL	*156.00 FL
10	1		*FRONT KNUCKLE CONTROL ARM LH	Not Necessary	467.00 FL	*- FL
11	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
12	1		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	30.00 FS	*- FS
13	1		*FRONT SPORT RIM	Warped	500.00 FS	*500.00 FS
14	1		*FRONT TYRE	Not Necessary	400.00 FS	*- FS
15	1		*FRONT BUMPER AND FENDER WRAPPER STICKER	Necessary	500.00 FS	*400.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	7,708.003,004.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	622.80205.40
					Total Parts (\$\$)	7,085.202,798.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RECTIFY ELECTRICAL FAULTS WHERE NECESSARY	New	60.00	20.00
2	TO REMOVE AND RENEW FRONT UNDER CARRIAGE	New	380.00	120.00
3	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
4	TO REMOVE AND REPLACE NEW WRAPPER	New	200.00	0.00
5	TO STRAIGHTEN ,REPAIR ,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	800.00	350.00
6	TO SPRAY PAINTING ON AFFECTED AREA	New	800.00	400.00
Gross Labour Cost (S\$)			2,390.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >