

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM22007238/Avy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Date:	17/10/2022	
	ATTN: HO WINNIE		Code	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 1670J	Veh. Inspected	SDY 9339K	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S2M047UG	Excess (\$)	0.00	
	Assign From	HO WINNIE	Assign Date	29/07/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA CAMRY	c.c	2494	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	MR053AK5004012723	Colour	GREY	
	Odometer	76987 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	MICHELIN	6 mm	
	L/H Front Tyre	215/55 R17	MICHELIN	6 mm	
	R/H Rear Tyre	215/55 R17	MICHELIN	6 mm	
	L/H Rear Tyre	215/55 R17	MICHELIN	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/07/2022	Inspection Date	01/08/2022	
	Survey held at 2020 SPRAY PAINTING PTE LTD				
	53 UBI AVENUE 1, #05-15, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	<u> </u>				