

TPAXA.

VERON.

SDY9339K. 2018 April

Toyota Camry 2494 CC

MR053AKS004012723

Front Bumper	Deband	543.90	✓
Front Bumper Clips.	new	30(SN)	✓
Front Bumper Side Holder RH.	2nd	65.40	✓
Front Bumper Reinforcement	new m	395.80	+
Front Bumper Sponge.	could	138.40	✓
Front Bumper Fog Lamp RH.	new m	337.20.	+
Front Bumper Lower Grille.	could	245.90	✓
Front Bumper Sensor RH.	2nd	245	✓
Front Bumper Air Vent RH	Deband	34.50	✓
Headlamp RH.	could	1885.40	✓
Front RH Fender	Deband	797.30	✓
Front RH Fender Inner Shield	new m	190.70	+
Front RH Fender Inner Shield	new m	Cups 30(SN)	+

SDY9339K.

Front RH Wheel Rim } MP
Front RH Tyre. } MR

850(SN) X

300(SN) X

Wiper Washer Tank. Del'd
Wiper Washer Tank Motor MP

145.10 ✓

150.40 X

Panel Beating

~~800~~ 500

Spray Painting.

~~800~~ 600

Wiring.

~~100~~ 50

To spray full coat

~~150~~ 40

To remove front bumper sensors

~~100~~ 50

To perform wheel alignment.

150 X.

8505.40

hist: 4121.30

Labour: 1240

len 25%: 3090.57

total: 4360.57

S-N: 30

f/s: 3.4k.

04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: