

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	SURANCE (S) PTE LTD		Ref:	CS3/CTI22007241/y3
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	29/07/2022
				Code:	СТІ
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBG 4040Y	Veh. Inspected		SMN 4940H
	Policy No.		Coverage (\$)		0.00
	Claim No.	SNM22D205285/C02/GBG4040 Y/TAYHP	Excess (\$)		0.00
	Assign From	IRENE TAY	Assign Date		29/07/2022
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	. Description of Damages				
5.	General Information				
	Accident Date	26/07/2022	Inspection Date)	
	Survey held at	V-TECH AUTO SERVICE			
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				