



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En AutomobileCHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Ref: CS/CTI22007245/Kvy3

Date: 30/07/2022

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 8592J	Veh. Inspected	SMN 7560B
Policy No.		Coverage (\$)	0.00
Claim No.	SNM22D205289/C02/CB8592J/ TANKL	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	29/07/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/07/2022	Inspection Date	01/08/2022
Survey held at	160 Sin Ming Drive • #06-02 Sin Ming AutoCity		
Repairer	MBM WHEELPOWER PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
