



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22003671/Kcy3e2-1 Date: 03/08/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 6335Z	Veh. Inspected	SNA 7584P
	Policy No.	D21MTPV01008072	Coverage (\$)	0.00
	Claim No.	CMTD2201302/AGC	Excess (\$)	0.00
	Assign From	AGNES CHAN	Assign Date	25/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053REH104540578	Colour	METALLIC GREY
	Odometer	111640 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	BRIDGESTONE	2 mm
	L/H Front Tyre	215/45 R17	BRIDGESTONE	2 mm
	R/H Rear Tyre	215/45 R17	BRIDGESTONE	2 mm
	L/H Rear Tyre	215/45 R17	BRIDGESTONE	2 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/04/2022	Inspection Date	21/04/2022
	Survey held at	KING'S AUTO REPAIR & SERVICE PTE LTD 176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	