



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/08/2022
User ID : PohSuan
Section A - Accident Details

Registration Number	SHB5322H
Case Reference Number	TAX/07/22/2079
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	NG KIM HENG (HUANG JINXING)
Type of Accident	Side Swipe
Accident Date and Time	23/7/2022 12:30 AM
Accident Reported Date and Time	25/7/2022 3:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115707
Special Instruction to ARC, if any	RIGHT REAR PORTION / CHINA TAIPING
Prepared Date and Time	29/7/2022 8:58 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$700.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$5,421.51	\$1,481.95
Total Other Cost	\$620.00	\$100.00
TOTAL COST	\$8,171.51	\$2,681.95 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / China Taiping
ARC / Surveyor Sign Off Date	04/08/2022 2:17 PM	04/08/2022 2:49 PM
Signature		
Remarks	Total number of repair days = 5 days. SUP = 0 day.	Part by part, take before spray

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/08/2022

User ID : PohSuan

		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$261.00	0.00	\$0.00	Replace	Not Given	X	} nn	
		81580-47070	LAMP ASSY, REAR, RH	0.00	\$293.60	0.00	\$0.00	Replace	Not Given	X		} nn
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X		
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$871.50	25.00	\$653.63	Replace	Replace	√	dd	
		6556547010	PATCH, SIDE PANEL REAR END , RH & LH	1.00	\$33.70	25.00	\$25.28	Replace	Replace	√	br	
		65637-47060	LINER, REAR FENDER , RH	0.00	\$139.80	0.00	\$0.00	Replace	Not Given	X	} nn	
		62940-47010	DUCT ASSY, QUARTER VENT , RH & LH	0.00	\$67.00	0.00	\$0.00	Replace	Not Given	X		} nn
		62331-47050	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	0.00	\$293.00	0.00	\$0.00	Replace	Not Given	X		
		62551-47020-C0	GARNISH, REAR SEAT SIDE, RH	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X	} nn	
		4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X		} nn
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X		
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$668.90	0.00	\$0.00	Replace	Not Given	X	} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn
											} nn	
												} nn

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$339.60	10.00	\$305.64	Replace	Replace
Total					339.60		305.64		

1,481.95
+ 700.00
+ 500.00

2,681.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

EzLyna (LKKAuto)

From: Yeo Poh Suan (Strides Automotive Services Pte Ltd) <PohSuan.Yeo@strides.com.sg>
Sent: Friday, 11 November 2022 5:36 PM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5322H
Attachments: SHB5322H(TAX07.22.2079).pdf; DSCN0222.jpg; DSCN0224.jpg; DSCN0223.jpg; DSCN0225.jpg; DSCN0220.jpg

Hi Steve,

Attached herewith the repair estimate of SHB5322H having Case No: TAX/07/22/2079.

There is no change to the approved amount of \$2,681.95 @ 5 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Yeo Poh Suan
Strides Automotive Services
PohSuan.Yeo@strides.com.sg

