



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMZ3898R

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **58604**
Reg No/Reg Date **SMZ3898R / 19/04/2021**
Date In/Mileage **/ 0**
Chassis No **W1N2539802F9072277**
Engine No **26492030356470**
Make/Model **MB/GLC 200**
Colour/Trim **021 197 Obsidian B1/ 041 128 ARTICO Magm**

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	29/07/2022/ 11:33	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : DMPCSNW00069952200 // 29-07-2022 DRIVE IN: 29-07-2022 // TP CAR NO: YN1523G (LONPAC INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT							0.10	380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT								120.00
A BPILAB REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR								1440.00
A BPILAB CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM								180.00
A BPILAB BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS								120.00
A BPILAB REMOVE & REPLACE REAR BUMPER, REAR LEFT FENDER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.								5760.00
A BPIRES RESPRAY REAR BUMPER, REAR LEFT FENDER & REAR END PANEL								2400.00
S BPNSUB SUPPLY 1PC REAR LEFT FENDER 3/4 GLASS SOLAR FILM PURCHASE ORDER NO:								100.00
M LH/R TAIL LAMP					1.00	533.10	00.00	533.10
M REAR BUMPER					1.00	1002.77	00.00	1002.77
M REAR BUMPER BOTTOM PANEL					1.00	535.33	00.00	535.33
M REAR BUMPER BOTTOM PANEL CHROME					1.00	780.48	00.00	780.48
M LH/R BUMPER SIDE BRACKET					1.00	165.24	00.00	165.24
M LH/R OUTER PARKING SENSOR					1.00	195.43	00.00	195.43
M LH/R PARKING SENSOR SEAL					1.00	7.10	00.00	7.10
M LH/R FENDER					1.00	3452.02	00.00	3452.02

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMZ3898R

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **58604**
Reg No/Reg Date **SMZ3898R / 19/04/2021**
Date In/Mileage **/ 0**
Chassis No **W1N2539802F9072277**
Engine No **26492030356470**
Make/Model **MB/GLC 200**
Colour/Trim **021 197 Obsidian Bl/ 041 128 ARTICO Magm**

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	29/07/2022/ 11:33	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LH/R FENDER AIR FLAP	1.00	53.78	00.00	53.78
M LH/R FENDER SIDE TRIM	1.00	256.65	00.00	256.65
M LH/R WHEEL ARCH	1.00	216.69	00.00	216.69
M LH/R FENDER 3/4 GLASS	1.00	422.92	00.00	422.92
M GLAZING REPAIR KIT	1.00	179.31	00.00	179.31
M ADHESIVE SEALANT	1.00	858.76	00.00	858.76
M SEAM SEALANT	1.00	116.07	00.00	116.07
M CAVITY WAX PROTECTION	1.00	116.04	00.00	116.04
M REAR CROSS MEMBER	1.00	850.57	00.00	850.57

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **20,242.26**
7% GST on **20242.26** **1416.96**

Total Payable 21,659.22

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG