



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SMZ3898R

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Steve

Vehicle & Document Information

WIP No 58604
Reg No/Reg Date SMZ3898R / 19/04/2021
Date In/Mileage 01/08/2022/ 42060
Chassis No W1N2539802F9072277
Engine No 26492030356470
Make/Model MB/GLC 200
Colour/Trim 021 197 Obsidian B1/ 041 128 ARTICO Magm

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WL001605	Credit	26/09/2022/ 23:19	AQ	305 / Alan Quek Ai Lun					
<p>M BPNSUN POLICY NO/ACC DATE : DMPCSNW00069952200 // 29-07-2022 DRIVE IN: 29-07-2022 // TP CAR NO: YN1523G (LONPAC INSURANCE) DATE IN/DATE SURVEY: 01-08-2022 // LKK STEVE BY/AUTHORIZED ON : HSIAO TONG // 01-08-2022</p>									
A BPILAB					USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB					CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT				120.00
A BPILAB					REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR				960.00
A BPILAB					CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM				180.00
A BPILAB					BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS				120.00
A BPILAB					REMOVE & REPLACE REAR BUMPER, REAR LEFT FENDER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				4320.00
A BPIRES					RESPRAY REAR BUMPER, REAR LEFT FENDER & REAR END PANEL			0.02	2000.00
S BPNSUB					SUPPLY AND INSTALL 1 PC HUPER OPTIK WINDOW FILM ON: LH REAR QUARTER PANEL D/O NO: AE/09444				100.00
X					LH/R TAIL LAMP	1.00	533.10	00.00	533.10
X					REAR BUMPER	1.00	1002.77	00.00	1002.77
X					REAR BUMPER BOTTOM PANEL	1.00	535.33	00.00	535.33
X					LH/R PARKING SENSOR SEAL	1.00	7.10	00.00	7.10
X					LH/R FENDER	1.00	3452.02	00.00	3452.02
X					LH/R FENDER SIDE TRIM	1.00	256.65	00.00	256.65
X					LH/R FENDER 3/4 GLASS	1.00	422.92	00.00	422.92

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMZ3898R

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **58604**
Reg No/Reg Date **SMZ3898R / 19/04/2021**
Date In/Mileage **01/08/2022/ 42060**
Chassis No **W1N2539802F9072277**
Engine No **26492030356470**
Make/Model **MB/GLC 200**
Colour/Trim **021 197 Obsidian Bl/ 041 128 ARTICO Magm**

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	26/09/2022/ 23:19	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X GLAZING REPAIR KIT	1.00	179.31	00.00	179.31
X ADHESIVE SEALANT	1.00	858.76	00.00	858.76
X SEAM SEALANT	1.00	116.07	00.00	116.07
X CAVITY WAX PROTECTION	1.00	116.04	00.00	116.04
X BASIC MOUNTING FOR BUMPER	1.00	46.59	00.00	46.59
X LH/R BUMPER SIDE BRACKET	1.00	165.24	00.00	165.24
X PLUG	2.00	2.70	00.00	5.40

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 15,877.30
7% GST on 15877.30 1111.41

Authorized signatory and company stamp

Total Payable 16,988.71

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg