

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jul 2022)  
 Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: ComfortDelGro Engineering Pte Ltd/SHC3416D/26/07/2022 16:04  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	<del>fu</del> *459.40 FL
2	1		*REAR BUMPER CLIPS	20.00	0.00	<del>net</del> *22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	<del>de</del> *451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	<del>R</del> *394.80 FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00	<del>R</del> *138.10 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	<del>R</del> *138.10 FL
7	1		*REAR BUMPER LOWER CTR MOULDING	20.00	0.00	<del>cu</del> *155.00 FL
8	1		*ANTENNA SMARTKEY	20.00	0.00	<del>R</del> *40.50 FL
9	1		*REAR BUMPER FOG LAMP	20.00	0.00	<del>x</del> *201.50 FL
10	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	<del>R</del> *180.00 F
11	1		*REAR NUMBER PLATE WITH TRIM COVER	0.00	0.00	<del>cr</del> *55.00 F
12	1		*REAR BUMPER RUBBER MAT	0.00	0.00	<del>net</del> *50.00 F

=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,285.65</b>
- List Item Discount on L Items (\$\$)	400.13
<b>Total Parts (\$\$)</b>	<b>1,885.52</b>

ComfortDelGro Engineering Pte Ltd/SHC3416D/26/07/2022 16:04. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

1087.65  
 20% - 870.12  
 8N 105

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (\$)</b>			<b>11.00</b>

11

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	350 550.00
2	SPRAY PAINTING CHARGE	New	250 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
<b>Gross Labour Cost (\$)</b>			<b>630 910.00</b>

ComfortDelGro Engineering Pte Ltd/SHC3416D/26/07/2022 16:04. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Temp No 97495749  
 27/12/22 R fpu  
 2 days  
 1/3 Resurvey after repair  
 temp No 97495749

870.12  
 105  
 11  
 630  
 -----  
 1616.12  
 4591300  
 \* 2 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: