

SMN786M.

Toyota Vellfire 3456cc.

G6H300006357.

TPAIG.

Xiao Tony.

July 22.

Rear Bumper	Deformed.	1759.40 ✓
Rear Bumper Clips.	new	30(SN) ✓
Rear Bumper Side Holder	x 02 ^{new}	65.1 x 2 = 130.20 +
Rear Bumper Tow Cover.	Missing LH cracked	34.50 ✓
Rear Bumper Side Reflector	x 02.	59.8 x 2 = 119.60
		880(SN).
Rear Bumper Lower Spoiler	Dehd	1200(SN).
Rear Bumper Undercover LH.	Dehd	290.70. ✓
Rear Bumper Undercover Clips.	new	20(SN) ✓
Rear Bumper Impact Bracket	x 02. ^{new}	69.2 x 2 = 138.40 +
		870
Reverse Sensor	x 04. ^{3 pieces damaged}	290 x 4 = 1160.
Reverse Sensor Holder	x 04. ^{new}	25 x 4 = 100 ✓
Reverse Sensor Wire Harness.	^{new}	288.10 +
Rear End Panel.	Dented	781.90 ✓

SMN 786M.

Reer End Panel Top Garnish.	Del'd	245.40	✓
Reer End Panel Top Garnish Clips	m	20(SN)	✓
Reer End Panel Sealant.	m	60(SN)	✓
Reer End Panel Antenna Sensor	MP re	155.40	X
Reer End Panel Buzzer.		124.20	X.
		689.20	✓
Taillamp LH.	Lt		
Taillamp Lower Apron LH.	Del'd	348.60	✓
		1905	
Tailgate	Dented	2040.50	✓
Tailgate Lock.	Damaged	498.40.	✓
Tailgate Auto Lock Motor	MP m	2812.70.	X
Tailgate Weatherstripe	Cut	324.70.	✓
Tailgate Auto Lock Side Sensor.	NE m	745.1 X 2 = 1490.20.	X.
Tailgate Inner Trim Board.	Del'd	734.50	✓
Tailgate Inner Trim Board Clips.	m	30(SN)	✓
Tailgate Reflector LH.	Lt	585.40.	✓

SMN786M.

Tailgate Glass Moulding?		185.40 ✓
Tailgate Glass Sealant.		60(SN). ✓
Vellfire Emblem	NEC	85.90 ✓
Executive Lounge Emblem.		90.40 ✓
V6 Emblem.		58.90 ✓
Rees Centre Rail x 22	new	$1230.1 \times 2 = 2460.20$ + 209.80
Rees Centre Rail Cover x 22.	LH Del'd	$209.8 \times 2 = 419.60$
Rees Centre Rail Utility Tray.	new	294.80 X 899.50
Rees Fender Inner Trim Board	LH Del'd	$899.5 \times 2 = 1799$
Rees Fender Lower Trim Board Clips.	new	30(SN) 60(SN)
Floor Panel.	Reps	818.20 +
Floor Panel Top Board LH.	Del'd	489.10 ✓
Floor Panel Top Centre Board.	new	281.90 +
Floor Panel Surround Mat.	new	755.30 +
Floor Panel Surround Mat Clips.	new	50(SN) X

SMN1786M.

Panel Beating	1600 1100
Spray Painting.	1400 1200.
Wiring.	100 30
To apply tuff coat.	150 80
To remove upholstery.	150 80
To remove reverse sensor	100 50
To remove rear camera.	100 50
To remove rear video-recorder.	100 50
To transfer tailgate fittings.	150 80
To remove tailgate glass.	180 120

List : 11066.50

len 25%. 8299.87

S.N 1130.

labours. 2840

total 12269.87

L/S : 9.8k

07 Days

9,800
7 days