

**Section A - Accident Details**

Registration Number	SHB144M
Case Reference Number	TAX/07/22/2071
Registration Date	28/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	MOHD SHARIFF BIN OMAR
Type of Accident	Side Swipe
Accident Date and Time	23/7/2022 4:30 PM
Accident Reported Date and Time	25/7/2022 9:01 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115694
Special Instruction to ARC, if any	TP/ LEFT REAR PORTION/ DROVE IN/NTUC - LKK
Prepared Date and Time	28/7/2022 2:25 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,674.00	\$780.00
Total Spare Part Cost	\$4,662.07	\$0.00
Total Other Cost	\$700.00	(\$230.00)
<b>TOTAL COST</b>	<b>\$7,881.07</b>	<b>\$850.00 (L/S)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	7.0	3.0
Prepared / Adjusted By	<b>Tuck Foo Kok</b>	<b>RASUL (LKK) / NTUC</b>
ARC / Surveyor Sign Off Date	<b>29/07/2022 9:28 AM</b>	<b>28/07/2022 5:12 PM</b>
Signature		
Remarks		LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO .

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2208-0079	<b>Invoice Number</b>	
<b>Quotation Date</b>	06.08.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$845.00	\$300.00
<b>Total Labour</b>	<b>\$845.00</b>	<b>\$300.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING LH	\$180.00	\$100.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$80.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,674.00</b>	<b>\$780.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$230.00)
<b>Total Other Costs</b>	<b>\$700.00</b>	<b>(\$230.00)</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700447210	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair
		7586047900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$576.00	100.00	\$0.00	Replace	Repair
		6563247080	PLATE, REAR WHEEL HOUSE, FRONT LH	0.00	\$26.80	0.00	\$0.00	Replace	Not Given
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$824.80	100.00	\$0.00	Replace	Repair
		6563847060	LINER, REAR FENDER, LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
		5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given

R  
R  
X  
R  
X  
X  
X  
X  
R  
X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/08/2022

User ID : PohSuan

	52462470 20	PAD, RR BUMPER, RH & LH , 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given	X
	52462470 10	PAD, RR BUMPER, RH & LH , 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given	X
	52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given	X
	52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X
	52592470 40	SEAL, RR BUMPER , LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given	X
	52566479 00	FILLER, RR BUMPER , LH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	R
	52453470 10	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given	X
	52461470 10	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
	58399470 30	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>				<b>\$6,133.54</b>		<b>\$0.00</b>			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

	0.00	
+	300.00	
+	780.00	L/S \$850/-
	<u>1,080.00</u>	
	-20%	
	<u>864.00</u>	