



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22007272/Ucm4
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1			Date:	30/08/2022
HEMMANT ROADSINGAPORE 438675				
ATTN: HAFIZUL FARHAN			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 819R	Veh. Inspected	SVJ 3792T	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/047	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	01/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN LATIO SPORT (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1FAAC11Z0010874	Colour	SILVER	
Odometer	166924 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	7 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/07/2022	Inspection Date	01/08/2022	
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			15 Working Days	