



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22007274/Uqce2	
			Date: 12/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 8425D	Veh. Inspected	SND 5247K
	Policy No.	D22MTPV01009366	Coverage (\$)	0.00
	Claim No.	CMTD2202584/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	01/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDD2040312A811324	Colour	WHITE
	Odometer	214418 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/07/2022	Inspection Date	01/08/2022
	Survey held at	SM SPRAY PAINTING PTE LTD NO. 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KAKI BUKIT SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	