

nCar AUTOMOTIVE PTE LTD

toHub

Ave 2

8 /Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BENDY FONG CHEE LUP
BLK 697 HOUGANG ST 61 #12-24
SINGAPORE 530697

Contact : 93801194

TP Allianz.
VERON.

TAX INVOICE

Repair Code : CLM15612

Date in : 27/07/2022

Vehicle Num. : SLX7268E

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP71201635/LEB6541995

Parts and Labour Assesment

Description of part	Qty	Unit Price	985 Amount
REAR BUMPER <i>delnd</i>	1	1150.00	1,150.00
REAR BUMPER REFLECTOR GARNISH L/R <i>LH delnd</i>	2	45.00	90.00
REAR BUMPER REFLECTOR L/R <i>HT delnd</i>	2	45.00	90.00
REAR BUMPER SIDE RETAINER L/R <i>delnd</i>	2	26.50	53.00
REAR BUMPER SPONGE L/R <i>LH delnd</i>	2	89.50	179.00
REAR BUMPER TOW HOOK COVER <i>delnd</i>	1	16.50	16.50
REAR BUMPER UNDER COVER LH <i>delnd</i>	1	98.30	98.30
REAR BUMPER UNDER COVER RH <i>delnd</i>	1	95.20	95.20
REAR END PANEL <i>delnd</i>	1	560.80	560.80
REAR END PANEL INNER TOP GARNISH <i>delnd</i>	1	155.50	155.50
REAR TAILGATE <i>delnd</i>	1	1193.00	1,193.00
REAR TAILGATE 'HYBRID' EMBLEM <i>delnd</i>	1	75.80	75.80
REAR TAILGATE 'LOGO' EMBLEM <i>delnd</i>	1	38.00	38.00
REAR TAILGATE 'SHUTTLE' EMBLEM <i>delnd</i>	1	55.00	55.00
REAR TAILGATE HINGES L/R <i>delnd</i>	2	50.00	100.00
REAR TAILGATE INNER PULL HANDLE <i>delnd</i>	1	25.00	25.00
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>delnd</i>	2	18.50	37.00
REAR TAILGATE INNER TRIM BOARD <i>delnd</i>	1	320.00	320.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

BENDY FONG CHEE LUP
 BLK 697 HOUGANG ST 61 #12-24
 SINGAPORE 530697

Contact : 93801194

TAX INVOICE

Repair Code : CLM15612

Date in : 27/07/2022

Vehicle Num. : SLX7268E

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP71201635/LEB6541995

REAR TAILGATE LOCK STRIKER	3435.10	1	27.50	+	27.50
REAR TAILGATE MECHANISM LOCK		1	157.10	✓	157.10
REAR TAILGATE WEATHER STRIP	2762.48	1	168.50	✓	168.50
REAR TAILGATE WINDSCREEN MOULDING		1	120.00	✓	120.00
Subtotal before discount					4,805.20
Percentage discount 20%					961.04
Sub-total 1					3,844.16
REAR BUMPER CLIPS - SET		1	80.00	30	80.00
REAR BUMPER REVERSE SENSOR		1	280.00	20	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET		1	50.00	10	50.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET		1	40.00	30	40.00
REAR TAILGATE NUMBER PLATE		1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE HOLDER	330	1	50.00	+	50.00
REAR TAILGATE OUTER CHROME MOULDING WITH GARNISH CLIPS - SET		1	30.00	+	30.00
REAR TAILGATE WINDSCREEN SEALANT		1	80.00	60	80.00
Subtotal before discount					635.00
Percentage discount 0%					0.00
Sub-total 2					635.00
Parts-total					4,479.16

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BENDY FONG CHEE LUP
BLK 697 HOUGANG ST 61 #12-24
SINGAPORE 530697

Contact : 93801194

TAX INVOICE

Repair Code : CLM15612

Date in : 27/07/2022

Vehicle Num. : SLX7268E

Model : HONDA SHUTTLE HYBRID 1.5 AUTO

Chassis/Eng# : GP71201635/LEB6541995

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

✓ 80.00
600 100.00
600 1,000.00
650 600 1,000.00
60 120.00
✓ 80.00
2,380.00
6,859.16

*** This is a computer-generated document which requires no signature.***
page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian G
h/s 01/08/22
OSRys
Total: 4634.08
L/s: 3.7K
3.7K