

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 11 Jan 2023

Preliminary Advice

Vehicle No	: SFM7733H	Accident Date	: 27/07/2022
Make	: TOYOTA SIENTA	Policy No.	: SP2000702593
Assignment Date	: 30/07/2022	Excess	: S\$600.00
Date of Inspection	: 01/08/2022	Est. Duration of Repair	: 07
Inspection At	: KAN FOOK SING MOTOR WORKSHOP		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,080.50	(Inclusive of Supp \$1,518.00)
Revised Amount	:S\$	6,468.70	(Inclusive of Supp \$1,518.00)
Check Items (Estimated)	:S\$		
Total	:S\$	6,468.70	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	44,075.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,925.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Kindly approve on supplementary.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.