

KFS Motor

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
VEHICLE NO. : SFM7733H
ACCIDENT DATE : 27-07-2022 23:00
THIRD PARTY REF. : UNKNOWN

INVOICE NO : TEST
DATE : 29-08-2022

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEHICLE SFM7733H TOYOTA SIENTA

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT HEADLAMP RH	300.00
1	FRONT FENDER RH	160.00
1	FRONT FENDER SHIELD RH	75.00
10	FRONT FENDER SHIELD CLIP@\$2.50	25.00
1	FRONT BUMPER	150.00
1	FRONT BUMPER SIDE RETIANER RH	25.00
1	FRONT BUMPER FOGLAMP COVER RH	60.00
10	FRONT BUMPER CLIP@\$1.20	12.00
1	FRONT DOOR RH	390.00
1	FRONT SHOCK ABSORBER RH	185.00
1	FRONT LOWER ARM RH	210.00
1	FRONT KNUCKLE ARM RH	150.00
1	FRONT KNUCKLE BEARING RH	50.00
1	FRONT STABILZIER LINK RH	60.00
1	FRONT DRIVE SHAFT RH	585.00
1	STEERING TIE ROD END RH	40.00
1	FRONT WHELL RIM	150.00
1	FRONT HUP CAP RH	110.00
1	FRONT CROSS MEMBER ASSY	750.00 *
1	FRONT WHEEL BEARING HUB RH	110.00 *
1	FRONT BRAKE CALLIPER (RH)	260.00 *
10	FRONT DOOR RIVET @\$1.50	15.00 *
1	FRONT SPEED SENSOR (RH)	150.00 *
1	FRONT BONNET CABLE	30.00 *
1	FRONT BRAKE DISC ROTOR COVER	65.00 *

VEHICLE NO. : SFM7733H
ACCIDENT DATE : 27-07-2022 23:00
THIRD PARTY REF. : UNKNOWN

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
		4117.00
	ADD 10 %	411.70
	TOTAL (A)	<u>4528.70</u>

SPECIAL NETT ITEMS

1	FRONT TYRE RH	200.00
	TOTAL (C)	<u>200.00</u>

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO CHECK ALIGNMENT	80.00
1	TO REMOVE/REFIT FRONT UNDERCARRIAGE RH	180.00
1	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	50.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	600.00
1	SPRAYPAINTING CHARGES	800.00
	TOTAL (D)	<u>1,740.00</u>
	TOTAL REPAIR COST :	<u>6468.70</u>
	G S T % :	410.81
	EXCESS AMOUNT :	600.00
	INVOICE AMOUNT :	<u>6279.51</u>

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2022)

Parts: M1-MPV TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SFM7733H/29/07/2022 14:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT HEADLAMP RH <i>Cracked</i>	0.00	0.00	300 *310.00 F	✓
2	1		*FRONT HEADLAMP TOP PANEL RH <i>Cracked</i>	0.00	0.00	*40.00 F	✓
3	1		*FRONT FENDER RH <i>Cracked</i>	0.00	0.00	160 *155.00 F	✓
4	1		*FRONT FENDER SHIELD RH <i>torn</i>	0.00	0.00	75 *80.00 F	✓
5	10		*FRONT FENDER SHIELD CLIP <i>in</i>	0.00	0.00	*25.00 F	✓
6	1		*FRONT FENDER 1/4 GARNISH RH <i>?</i>	0.00	0.00	*45.00 F	?
7	1		*FRONT BUMPER <i>Cracked</i>	0.00	0.00	150 *170.00 F	✓
8	1		*FRONT BUMPER SIDE RETAINER RH <i>Missing</i>	0.00	0.00	25 *30.00 F	✓
9	1		*FRONT BUMPER FOGLAMP COVER RH <i>Missing</i>	0.00	0.00	*45.00 F	✓
10	1		*FRONT BUMPER LOWER COVER <i>torn</i>	0.00	0.00	*60.00 F	✓
11	10		*FRONT BUMPER CLIP <i>in</i>	0.00	0.00	12 *25.00 F	✓
12	1		*FRONT DOOR RH <i>Door Defect</i>	0.00	0.00	390 *450.00 F	✓
13	1		*FRONT DOOR HINGE TOP RH <i>?</i>	0.00	0.00	*40.00 F	+
14	1		*FRONT DOOR HINGE LOWER RH <i>?</i>	0.00	0.00	*40.00 F	+
15	1		*FRONT DOOR CHECKER RH <i>?</i>	0.00	0.00	*65.00 F	?
16	1		*FRONT SHOCK ABSORBER RH <i>?</i>	0.00	0.00	*185.00 F	?
17	1		*FRONT SHOCK ABSORBER MOUNTING RH <i>?</i>	0.00	0.00	*55.00 F	?
18	1		*FRONT LOWER ARM RH <i>?</i>	0.00	0.00	*210.00 F	?
19	1		*FRONT KNUCKLE ARM RH <i>?</i>	0.00	0.00	*150.00 F	?
20	1		*FRONT KNUCKLE BEARING RH <i>?</i>	0.00	0.00	*50.00 F	?
21	1		*FRONT STABILIZER LINK RH <i>?</i>	0.00	0.00	*60.00 F	?
22	1		*FRONT DRIVE SHAFT RH <i>New</i>	0.00	0.00	*585.00 F	+
23	1		*STEERING RACK AND PINION <i>?</i>	0.00	0.00	*580.00 F	?
24	1		*STEERING TIE ROD END RH <i>?</i>	0.00	0.00	*40.00 F	?
25	1		*FRONT WHEEL RIM RH <i>Cracked</i>	0.00	0.00	*150.00 F	✓
26	1		*FRONT HUP CAP RH <i>Missing</i>	0.00	0.00	*110.00 F	✓

F=Franchise part.

Sub Total (S\$)	3,755.00
+ Margin on L,N Items 10.00% (S\$)	375.50
Total Parts (S\$)	4,130.50

Kan Fook Sing Motor Workshop/SFM7733H/29/07/2022 14:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FRONT TYRE RH

Resolved.

200

~~250.00~~

Sub Total (\$\$)

250.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 SPRAYPAINTING CHARGES

New

~~1,100.00~~

2

Labour Items

2 TO CHECK WIRING SYSTEM

New

~~50.00~~

3

3 TO CHECK ALIGNMENT

New

~~100.00~~

2

4 TO REMOVE/REFIT FRONT UNDERCARRIAGE RH

New

~~180.00~~

2

5 TO TRANSFER DOOR MECHANICISM TO NEW DOOR

New

~~50.00~~

2

TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

New

~~680.00~~

600

Gross Labour Cost (\$\$)

2,160.00

Kan Fook Sing Motor Workshop/SFM7733H/29/07/2022 14:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian King
7/17 OT Days
01/08/22
Not Authorised
Excess \$600
96893735

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 20 Oct 2022)**Parts:** M1-MPV TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Kan Fook Sing Motor Workshop/SFM7733H/20/10/2022 10:16**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT CROSS MEMBER ASSY	0.00	0.00	*750.00 F
2	1		*FRONT WHEEL BEARING HUB RH	0.00	0.00	*110.00 F
3	1		*FRONT BRAKE CALLIPER RH	0.00	0.00	*260.00 F
4	10		*FRONT DOOR RIVET	0.00	0.00	*15.00 F
5	1		*FRONT SPEED SENSOR RH	0.00	0.00	*150.00 F
6	1		*FRONT BONNET CABLE	0.00	0.00	*30.00 F
7	1		*FRONT BRAKE DISC ROTOR COVER	0.00	0.00	*65.00 F

F=Franchise part.

Sub Total (\$\$)	1,380.00
+ Margin on L,N Items 10.00% (\$\$)	138.00
Total Parts (\$\$)	1,518.00

Kan Fook Sing Motor Workshop/SFM7733H/20/10/2022 10:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/SFM7733H/20/10/2022 10:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >