



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2207305  
INV Date 25/11/2022  
Reference CC4/LPC22007285/Epa3q2  
Code LPC2

#### PROFESSIONAL SERVICE FEE

Vehicle No. XE 4950X  
Insured Veh. GBA 9511D  
Claim No. 22/22/22/VC05/026087  
Policy No. Z22VC05011734  
Accident Date 28/07/2022  
Inspection Date 02/08/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC22007285/Epa3q2

Date: 25/11/2022

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBA 9511D	<b>Veh. Inspected</b>	XE 4950X
<b>Policy No.</b>	Z22VC05011734	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	22/22/22/VC05/026087	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GERALD	<b>Assign Date</b>	01/08/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	UD TRUCKS GKB5ALDHCQA	<b>c.c</b>	10836
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	JNCMBP0A1KU042020	<b>Colour</b>	BLUE
<b>Odometer</b>	270131 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	295/80 R22.5	GOODYEAR	5 mm
<b>L/H Front Tyre</b>	295/80 R22.5	GOODYEAR	5 mm
<b>R/H Rear Tyre</b>	295/80 R22.5	GOODYEAR	5 mm
<b>L/H Rear Tyre</b>	295/80 R22.5	GOODYEAR	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	28/07/2022	<b>Inspection Date</b>	02/08/2022
<b>Survey held at</b>	SIN SHENG AUTO WORKSHOP PTE LTD 5 TUAS AVENUE 3, SINGAPORE 639405		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 4950X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	AIR TANK	DENTED	2,995.50	2,995.50
2	AIR TANK BRACKET @\$477.50	BENT	955.00	955.00
2	AIR TANK U-BOLT @\$355.50	BENT	711.00	711.00
1	HOLDER, REAR LICENSE PLATE	BENT	467.50	467.50
1	LAMP ASSY, LICENSE PLATE	BROKEN	125.50	125.50
1	CROSSMEMBER CHASSIS FRAME	TO REPAIR SEE LABOUR	785.50	-
1	COCK, AIR TANK DRAIN	NOT NECESSARY	295.50	-
1	CHECK VALVE CLUTCH AIR LINE	NOT NECESSARY	225.50	-
	LESS 30% DISCOUNT		-1,968.30	-1,576.35
			4,592.70	3,678.15
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	BENT	20.00	20.00
1	RED STICKER (SN)	NECESSARY	40.00	40.00
			60.00	60.00
<b>LABOUR</b>				
	TO PANEL BEAT / REPAIR REAR BODY. INCLUSIVE OF THE REPAIR OF CROSSMEMBER CHASSIS FRAME. }		950.00	600.00
	TO DISMANTLE / REPLACE ABOVE-MENTIONED PARTS. }		-	-
	TO SPRAY PAINTING ON AFFECTED AREAS.		400.00	200.00
			1,350.00	800.00
<b>GRAND TOTAL</b>			<b>6,002.70</b>	<b>4,538.15</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,538.15</b>

Report Ref No. CC4/LPC22007285/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. XE 4950X

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 4950X

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

