

# SIN SHENG AUTO WORKSHOP PTE LTD

REGISTRATION NO.: 202019500G  
 NO. 5 TUAS AVE 3 SINGAPORE 639405

TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

Pioneer Districentre Pte Ltd

10 Tuas Avenue 13  
 Singapore 638983

Attn: Motor Claims Department

Estimate No : ES2022/0070  
 Date : 02/08/2022  
 Vehicle No : XE4950X  
 Make/Model : UD / GKB5A  
 Date of Accident : 28/07/2022  
 Prepared By : Hoe

S/N	Description	Qty	Unit Amount (\$\$)	Amount (\$\$)
<u>Parts</u>				
1	Air tank / <i>OD</i>	1	2,995.50	2,995.50 /
2	Air tank bracket / <i>BT</i>	2	477.50	955.00 /
3	Air tank u-bolt / <i>BT</i>	2	355.50	711.00 /
4	Holder, rear license plate / <i>BT</i>	1	467.50	467.50 /
5	Lamp assy, license plate / <i>BR</i>	1	125.50	125.50 /
6	Crossmember chassis frame / <i>X R</i>	1	785.50	785.50 X
7	Cock, air tank drain / <i>X MD</i>	1	295.50	295.50 X
8	Check valve clutch air line / <i>X MD</i>	1	225.50	225.50 X
				<u>6,561.00</u> <i>5254.50</i>
			Less : 30%	<u>(1,968.30)</u> <i>-30%</i>
			Parts total	<u>4,592.70</u> <i>3678.15</i>
<u>Special nett</u>				
1	Rear number plate / <i>BT</i>		20.00	20.00 /
2	Red sticker / <i>APC</i>		40.00	40.00 /
			Parts total	<u>4,652.70</u> <i>60</i>
<u>Labour charges</u>				
	To panel beat/repair rear body		950.00	<i>600</i>
	To dismantle/replace above-mentioned parts		400.00	<i>200</i>
	To spray painting on affected areas		<u>1,350.00</u>	<i>860</i>
				<i>= 4538.15</i>

Loss of Use : 4 days @ \$5220/day

*Star (LKK)*  
*2/8/22, 10.30*  
*m k*  
*PIP*  
*by RL y*  
*3 dy*

TOTAL

6,002.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- To provide correct information
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: