

# Premium Carz Services Pte Ltd

Co. Reg. No.: 201416720C  
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
Tel : 6636 9100 Fax : 6636 9113

Date : 29/07/2022

*Xiao Tang*

TO: Allianz Insurance Singapore Pte Ltd  
79 Robinson Road  
#09-01  
Singapore 068897

Our Customer : Glamour Auto Pte Ltd  
Vehicle No : SLW5729K  
Model : Honda Shuttle Hybrid 1.5 Auto  
Manufacture Year : 2018  
Date of Accident : 29/07/2022  
Total Estimate Repair Days : 5  
Total Pages : 2

Attn : Motor Claims Department  
Email : claims@allianz.com.sg

Re: Repair Estimate For Third Party Claim against SLK1281Z

| No.       | Item Descriptions                                                                                         | Qty | Unit Price             | Amount            | Remarks From Surveyor |
|-----------|-----------------------------------------------------------------------------------------------------------|-----|------------------------|-------------------|-----------------------|
| <b>A.</b> | <b>Spare Parts</b>                                                                                        |     |                        |                   |                       |
| 1         | Tail gate <i>Rented</i>                                                                                   | 1   | \$1,295.20             | \$1,295.20        | -1180 X SN: 200       |
| 2         | Tail gate lock <i>Dead</i>                                                                                | 1   | \$96.60                | \$96.60           | ✓                     |
| 3         | Tail gate lower catch <i>new</i>                                                                          | 1   | \$24.70                | \$24.70           | +                     |
| 4         | Tail gate weatherstrip <i>new</i>                                                                         | 1   | \$168.50               | \$168.50          | +                     |
| 5         | Tail gate trimboard <i>new</i>                                                                            | 1   | \$320.80               | \$320.80          | +                     |
| 6         | Tail gate "H" logo <i>new</i>                                                                             | 1   | \$38.20                | \$38.20           | +                     |
| 7         | Tail gate "Shuttle" emblem <i>new</i>                                                                     | 1   | \$55.20                | \$55.20           | ✓                     |
| 8         | Tail gate "Hybrid" emblem <i>new</i>                                                                      | 1   | \$88.00                | \$88.00           | ✓                     |
| 9         | Rear bumper <i>Rented</i>                                                                                 | 1   | \$1,180.40             | \$1,180.40        | -1050                 |
| 10        | Rear bumper side retainer RH <i>new</i>                                                                   | 1   | \$26.50                | \$26.50           | ✓                     |
| 11        | Rear bumper side retainer LH <i>new</i>                                                                   | 1   | \$26.50                | \$26.50           | ✓                     |
| 12        | Rear bumper tow hook cover <i>new</i>                                                                     | 1   | \$26.50                | \$26.50           | +                     |
| 13        | Rear bumper reflector garnish RH <i>new</i>                                                               | 1   | \$45.20                | \$45.20           | +                     |
| 14        | Rear bumper reflector garnish LH <i>new</i>                                                               | 1   | \$45.20                | \$45.20           | +                     |
| 15        | Rear bumper reflector RH <i>new</i>                                                                       | 1   | \$45.60                | \$45.60           | +                     |
| 16        | Rear bumper reflector LH <i>new</i>                                                                       | 1   | \$45.60                | \$45.60           | +                     |
| 17        | Rear windsreen moulding <i>new</i>                                                                        | 1   | \$228.00               | \$228.00          | ✓ 1570.80             |
|           |                                                                                                           |     | <b>Sub-Total</b>       | <b>\$3,756.70</b> |                       |
|           |                                                                                                           |     | <b>Less 20%</b>        | <b>\$751.34</b>   |                       |
|           |                                                                                                           |     | <b>Total</b>           | <b>\$3,005.36</b> | 1256.64               |
|           |                                                                                                           |     |                        |                   | 8.11.2020             |
| <b>A.</b> | <b>Spare Parts (S/Nett)</b>                                                                               |     |                        |                   |                       |
| 1         | Rear number plate w/casing <i>new</i>                                                                     | 1   | \$70.00                | \$70.00           | +                     |
| 2         | Sealant <i>new</i>                                                                                        | 1   | \$80.00                | \$80.00           | -60                   |
| 3         | Rear bumper clip <i>new</i>                                                                               | 10  | \$5.00                 | \$50.00           | -30                   |
| 4         | Tail gate trimboard clip <i>new</i>                                                                       | 16  | \$5.00                 | \$80.00           | +                     |
| 5         | Reverse sensor (Set) <i>new</i>                                                                           | 1   | \$250.00               | \$250.00          | 200                   |
|           |                                                                                                           |     | <b>Sub Total 2</b>     | <b>\$530.00</b>   |                       |
|           |                                                                                                           |     | <b>Total for Parts</b> | <b>\$3,535.36</b> | 290                   |
| <b>B.</b> | <b>Labour</b>                                                                                             |     |                        |                   |                       |
| 1         | To check wiring.                                                                                          |     |                        | \$60.00           | 30                    |
| 2         | Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas. |     |                        | \$600.00          | 400                   |
| 3         | Spray painting all affected parts & areas.                                                                |     |                        | \$600.00          | 400                   |

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

| No. | Item Descriptions                          | Qty | Unit Price | Amount            | Remarks From Surveyor |
|-----|--------------------------------------------|-----|------------|-------------------|-----------------------|
| 4   | To spray anti-rust undercoat.              |     |            | \$50.00           | 30                    |
| 5   | To remove and refit rear windscreen glass. |     |            | \$120.00          | ✓                     |
|     | <b>Total Labour</b>                        |     |            | <b>\$1,430.00</b> |                       |
|     |                                            |     |            |                   |                       |
|     | <b>Total Repair Cost</b>                   |     |            | <b>\$4,965.36</b> |                       |

980

Adrian Lj  
R/S 03/08/22

04 Days

total: 3470.64

L/S: 2.7K.

total: 2726.64

L/S: 2.0K  
H

Yours faithfully,

Aun Teng  
f Premium Carz Services Pte Ltd

| Surveyor's Details |                           |
|--------------------|---------------------------|
| Name               |                           |
| Contact            |                           |
| Survey Date        |                           |
| Recommender        | Authorize / Not Authorize |
| Before Paint       | Yes / No                  |