

(08/11/13) wef

ASS. REC. BY: Marcus

REF:


CS/SM022007298/4gc

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMN 9427R
at Workshop m/s R.
of _____
Insured: SLD196E
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: R80k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: L7A538969

6690
Vehicle: IN / OUT

Date / Time Action / Instruction 20/11/22

10/8/22 have G.4
L/S \$2600 informed Alex. (Chk to \$885.20, 65%)

Veh No: SMN 9427R Yr Regn: 02/09/19
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Honda Shuttle Hybrid 1496
Colour: Red Insured / Std / NI / NA
Sp. Reading: 282468 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: GP7 2003989
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/60R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 30/07/22 D.O.I. 1/8/22
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
M/S Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 4/8/2022
Date/Time, File Return to?

2) _____

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

____ S + RS. ____ SI

Photos

Others

TOTAL

Report Format : TP

Lump Sum / I.B.I. (\$) 2600

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Submit to us

Not Acknowledged
1/8/22
2/5 @ 2600
4 days

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SMN 9427R

1PC	REAR DOOR N/S	no/matched	981.20	\$1,120.20	✓
1PC	REAR FENDER N/S	R		\$1,188.10	X
1PC	REAR BUMPER	cut	936.00	\$1,071.90	✓
1PC	REAR BUMPER SIDE RETAINER N/S	11		\$45.00	X
1PC	REAR WHEEL HUB BEARING N/S	11		\$650.00	X
				\$4,075.20	

(20%)

S.NETT

1SET	REAR BUMPER CLIPS	new	\$40.00	✓
1PC	REAR SPORT RIM N/S	new	\$650.00	450
1SET	REAR DOOR FRAME BLACK STICKER N/S	new	\$60.00	✓
1PC	REAR DOOR VISOR N/S	new	\$50.00	✓

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	50
TO TRANSFER REAR DOOR MECHANISM	\$80.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	11 \$120.00	X
TO CONDUCT WHEEL ALIGNMENT	\$100.00	60
TO DISMANTLE & REFIX REAR UNDER CARRIAGE	11 \$180.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	350
TO PUTTY & SPRAY PAINTING	\$1,200.00	600
TOTAL	\$7,485.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1917.20
20%
1533.76
600
1140
3273.76
202
2619.