

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)60 Jalan Lam Huat, #07-43
Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

Kenneth

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	29/07/2022
Vehicle Reg. No.:	SNE2810Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Vehicle Reg. Date:	01/03/2022
Vehicle Colour:	RED	Chassis No:	VF1RFA00063211961
Engine No:	K9KF649D060176		
Odometer:	53431 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	<i>5 days</i>		

*Not within
Mercury Bepain*

Present Location: MUNICH AUTOCARE PTE LTD (HQ)

COST OF CLAIMS

Parts	
Miscellaneous Items	
Labour	
Paintwork Labour	
Towing	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Amount
21,148.73
87.00
2,830.00
0.00
0.00

Calculated Gross Total (S\$)	24,065.73
- Excess (S\$)	2,000.00
(S\$)	22,065.73
+ GST 7.00% (S\$)	1,544.60
Nett Amount (S\$)	23,610.33

This claim is handled by: TAN CHIN CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2022)
 Parts: M1-MPV RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Munich Autocare Pte Ltd/SNE2810Z/01/08/2022 14:01
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	*651004703R	FRONT BONNET	0.00	0.00	*1,509.76 F	✓
2	1	*656016673R	BONNET LOCK	0.00	0.00	*208.32 F	✓
3	1	*654000247R	FRONT BONNET HINGE RH	0.00	0.00	*150.41 F	✓
4	1	*654013594R	FRONT BONNET HINGE LH	0.00	0.00	*150.41 F	✓
5	1	*658408772R	FRONT BONNET INSULATOR	0.00	0.00	*330.62 F	X
6	1	*654704597R	FRONT BONNET DAMPER LH	0.00	0.00	*125.66 F	X
7	1	*654704597R	FRONT BONNET DAMPER RH	0.00	0.00	*125.66 F	X
8	1	*260101271R	FRONT HEADLAMP RH	0.00	0.00	*999.60 F	✓
9	1	*260602165R	FRONT HEADLAMP LH	0.00	0.00	*999.60 F	✓
10	1	*622907255R	FRONT CENTRE BRACE BRACKET	0.00	0.00	*148.84 F	✓
11	1	*620223972R	FRONT BUMPER	0.00	0.00	*1,877.34 F	✓
12	1	*625005785R	FRONT SUPPORT PANEL	0.00	0.00	*1,360.00 F	✓
13	4	*253A49995R	FRONT PARKING SENSOR	0.00	0.00	*2,496.24 F	✓
14	2	*2843896148R	FRONT BLIND SPOT SENSOR RH	0.00	0.00	*810.20 F	X
15	1	*623821034R	FRONT RADIATOR GRILLE BLACK	0.00	0.00	*296.80 F	✓
16	1	*623855072R	FRONT RADIATOR GRILLE MOULDING (CHROME)	0.00	0.00	*261.80 F	✓
17	1	*622561964R	FRONT RADIATOR GRILLE	0.00	0.00	*530.60 F	✓
18	1	*628905855R	FRONT GRILLE EMBLEM	0.00	0.00	*187.04 F	✓
19	1	*620363937R	FRONT RADIATOR TOP GARNISH	0.00	0.00	*513.40 F	✓
20	1	*752106346R	FRONT BUMPER REINFORCEMENT	0.00	0.00	*833.72 F	✓
21	1	*620901789R	FRONT BUMPER LOWER REINFORCEMENT GARNIS	0.00	0.00	*267.79 F	✓
22	1	*7711428130	COOLANT 5L	0.00	0.00	*27.10 F	✓
23	1	*921004063R	AIRCON CONDENSER	0.00	0.00	*1,041.60 F	✓
24	1	*144614EA1B	ENGINE INNER COOLER	0.00	0.00	*1,005.87 F	✓
25	1	*214105169R	RADIATOR	0.00	0.00	*812.44 F	✓
26	1	*214819674R	RADIATOR FAN COWLING ASSY	0.00	0.00	*1,049.66 F	✓
27	1	*628109433R	RADIATOR GRILLE INNER AIR DUCT	0.00	0.00	*185.13 F	✓
28	1	*215595656R	RADIATOR INNER AIR DUCT	0.00	0.00	*115.13 F	✓
29	1	*215586371R	INTERCOOLER AIR DUCT	0.00	0.00	*52.19 F	✓
30	1	*214F62853R	FRONT LOWER AIR INTAKE FLAP GUIDE	0.00	0.00	*669.08 F	✓
31	1	*656220664	front bonnet lock handle	0.00	0.00	*84.11 F	✓

F=Franchise part.

Sub Total (S\$)	19,226.12
+ Margin on L,N Items 10.00% (S\$)	1,922.61
Total Parts (S\$)	21,148.73

Munich Autocare Pte Ltd/SNE2810Z/01/08/2022 14:01. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	6	FRONT BUMPER SCREW	<i>Ma</i> 42.00 ✓
2	1	FRONT NUMBER PLATE	<i>Pm</i> 45.00 X
Sub Total (\$\$)			87.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPLACE / WELADING REALIGN FROT BUMPER , BONNET, FRONT WINDS SUB FRAME, CHASSISD MEMBER FRONT ASSY LH/RH AND ALL NECESSARY ETC	New	<i>500</i> 1,200.00
2	TO REMOVE & REPLACE RADIATOR FAN , HOSE AND AIR COND CONDENSER HOSE , FAN INLUDING VECUUM AND TOP UP GAS	New	<i>7</i> 250.00
3	TO DIAGNOSTIC SETTING PASSENGER & DRIVER RESTRAINT SYSTEM AND RESETING OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00 <i>7</i>
4	TO RESPRAY FRONT ACCIDENT PORTION, BONNET,FENDER LH & RH, BUMPER CHASSIS MEMBERASSY RH/LH AND NECESSARY ETC	New	<i>600</i> 1,000.00
Gross Labour Cost (\$\$)			2,830.00

Munich Autocare Pte Ltd/SNE2810Z/01/08/2022 14:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >